

#### Release note

Topic u-blox M9 ADR 5.15 firmware for ADR products

UBX-22037179 C1-Public

Author Georgi Gorine
Date 27 March 2023

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com. Copyright@ u-blox AG.

## Contents

1	General information	1
1.1	Scope	1
1.2	Related documentation	1
1.3	Software releases	2
1.3.1	External firmware image	2
2	New and improved features	2
2.1	New features	2
2.2	Improved features	2
3	Removed features	2
4	Message interface	2
4.1	UBX	2
4.2	New and modified messages	3
4.2.1	New messages	3
4.2.2	Modified messages	3
4.2.3	Removed messages	3
5	Known limitations and issues	3
5.1	TDK IAM 20680x sensor driver	3
5.2	Handling of inconsistent wheel tick or speed input	3
6	Open source software	4
7	Revision history	4

# 1 General information

# 1.1 Scope

This release note describes the u-blox M9 firmware image 1.00 ADR 5.15, designed to run on the following hardware products:

Modules: NEO-M9L-01A, NEO-M9L-20A

Chipset: UBX-M9140-KA-DR

# 1.2 Related documentation

- [1] u-blox M9 ADR 5.10 firmware Release notes, UBX-21051121
- [2] u-blox M9-ADR-5.15 Interface description, UBX-22037101
- [3] u-blox NEO-M9L Integration manual, <u>UBX-20048485</u>



#### 1.3 Software releases

## 1.3.1 External firmware image

Released firmware image for u-blox M9 products				
File	UBX_M9_100_ADR515.c8cc73e75bc135e83ce1713c42b70b7c.bin			
Firmware version	EXT CORE 1.00 (71d265), FWVER=ADR 5.15			
Protocol version	PROTVER=35.15			
ROM base support	ROM 1.02 - ROM BASE 0x118B2060			

# 2 New and improved features

## 2.1 New features

No new feature is introduced in this release. Refer to [1] for a list of new features that were made available in the previous release.

# 2.2 Improved features

This release introduces enhancements targeting the overall robustness of the u-blox M9 platform when operating in corner case scenarios. The key improvements to existing features are listed below:

- Enhanced the **dead reckoning (ADR/UDR) performance** by mitigating fly-aways and position jumps in corner case scenarios.
- Optimized the **advanced calibration handling** operation to mitigate position jumps when restoring UBX-MGA-SF after consecutive resets.
- Improved the **directionless odometer mode** when the input wheel tick quantization is very large (>> 1cm).
- Adapted the **course over ground value** in NMEA-GxRMC message to output values within 0-355.99 range.
- Corrected the **clock solution message** UBX-NAV-CLOCK to output updated values after reaching sensor fusion.

Please refer to the integration manual [3] for detailed information regarding these features.

## 3 Removed features

No feature has been removed in this release. Refer to [1] for a list of features that were removed in the previous release.

# 4 Message interface

# 4.1 UBX

This firmware now supports the **UBX Protocol Version 35.15**. Refer to [2] for details.



# 4.2 New and modified messages

The following modifications have been made compared to firmware 1.00 ADR 5.10:

#### 4.2.1 New messages

Message	Description / comment	
UBX-MON-SYS	Current system performance information, message output rate is configurable with new CFG-MSGOUT-UBX_MON_SYS_ *configuration items	
UBX-NAV2-SLAS	Support for a new message which outputs status information about SLAS corrections on secondary output. Message output rate configurable with new CFG-MSGOUT-UBX_NAV2_SLAS_* configuration items	
UBX-NAV2-TIMEQZSS	Support for new messages which output information about QZSS time in secondary output. Message output rate configurable with CFG-MSGOUT-UBX_NAV2_TIMEQZSS_* configuration items	
CFG-SBAS- IGN_HEALTH_FROM_PRNMASK CFG-SBAS-USE_IONOONLY	Ignore the health flag in the PRN mask Configuration to enable use of SBAS ionosphere correction only	
CFG-SEC-JAMDET_SENSITIVITY_HI	Enable to increase the sensitivity of jamming detection at the expense of increased false alarm rate	

## 4.2.2 Modified messages

Message	Description / comment
CFG-QZSS-SLAS_MAX_BASELINE	Maximum baseline increased to 350 km

## 4.2.3 Removed messages

Message	Description / comment
CFG-ITFM-ANTSETTING	Configuration for legacy interference monitor, this has been replaced
CFG-ITFM-BBTHRESHOLD	with simpler configuration interface
CFG-ITFM-CWTHRESHOLD	
CFG-ITFM-ENABLE	
CFG-ITFM-ENABLE_AUX	

# 5 Known limitations and issues

# 5.1 TDK IAM 20680x sensor driver

The TDK IAM 20680, 20680HT, 20680HP and 20680M sensors can fail during a self-test leading to the ESF-STATUS message reporting "missing data". This problem applies only to UBX-M9140-KA-DR chipset designs using these specific models of sensors.

**Workaround**: for chipset-based designs we recommend selecting an officially supported IMU or any other IMU from the "4.5 Supported sensor drivers" section in [1].

## 5.2 Handling of inconsistent wheel tick or speed input

Inconsistent WT (wheel tick or speed) input can lead to an unexpected receiver reset and a potential configuration reset to factory default values in RAM, BBR and flash. An exception string output (\$GNTXT,01,01,01,exception 0x00020002 has occurred\*2E) might be observed.



This happens during the WT scale factor estimation process and is typically seen when starting to drive. There are two scenarios that could trigger the issue:

- A. The WT input signal reflecting vehicle movement is not provided to the WT pin while the configuration item CFG-SFODO-USE\_WT\_PIN is set to 1 (true).
- B. The WT is provided as data via UBX-ESF-MEAS messages, but the data values do not indicate true speed or distance travelled.

## Workaround:

- 1. Configure CFG-SFODO-USE\_WT\_PIN to 0 (false) if the WT pin is not intended to be used by the application.
- 2. Refrain from sending inconsistent odometer data in UBX-ESF-MEAS which does not reflect the travelled distance.

# 6 Open source software

The u-blox M9 firmware image 1.00 ADR 5.15 does not contain any open source software components.

# 7 Revision history

Revision	Date	Name	Comments
R01	01-Nov-2022	ggor	First official release of ADR5.15 release notes
R02	27-Mar-2023	ggor	Added Section 5: Known limitations and issues