



## SIERRA WIRELESS END-OF-LIFE NOTICE5024

### OVERVIEW

---

DATE ISSUED:	September 30, 2022	TRACKING NUMBER:	4134953
PRODUCTS AFFECTED:	RC7620-1		
SKUS AFFECTED:	1104694, 1104842, 1104916, 1105018, 1105024, 1105067, 1105080		
BULLETIN:	TAC Range Update for the affected RC7620-1 SKUs		
FOR DISTRIBUTION TO:	All Customers		

### Summary

---

TAC Range Update for the affected RC7620-1 SKU's

### Details of Change

---

Due to the depletion of TAC code, 35363511, Sierra Wireless has updated all affected SKUs with a new TAC code, 35108065, implementing this change requires an update to SKU OEMPRI. Customers will observe a change to the range of the SKU OEMPRI, which will be advanced to distinguish the new version from the prior ones), otherwise no customer impact is expected. There is no change in the form, fit, and function of the module.

The OEMPRI's will be updated as noted below:

Product	SKU	Current SKU OEMPRI	New SKU OEMPRI
RC7620-1	1104694	001.003_000	001.004_000
RC7620-1	1104842	001.001_000	001.002_000
RC7620-1	1104916	001.001_000	001.002_000
RC7620-1	1105018	001.003_000	001.004_000
RC7620-1	1105024	001.001_000	001.002_000
RC7620-1	1105067	001.000_000	001.001_000
RC7620-1	1105080	001.000_000	001.001_000

### Effective Dates

---

The SKU OEMPRI update is expected to be implemented for the affected SKUs in September 2022.

### More information

---

For more information please contact your Sierra Wireless sales representative.