

MACOM
100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



30th July, 2024

Richardson RFPD, Inc.
1950 S. Batavia Ave, Suite 100
Geneva, Illinois 60134

ATTN: Quality/Purchasing Manager

PCN-01747

Subject: Adding additional inspection and testing site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional inspection and testing site for the parts listed in the next pages.

In addition to our current sites, we plan to inspect and test these parts at our long-standing Contract Manufacturer, Year 2000, Ho Chi Minh City, Vietnam. Year 2000 is a valued, high-quality manufacturing partner for many MACOM products.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely

Cindy Lien
Product Marketing Manager
cindy.lien@macom.com

PCN Number: PCN-01747		PCN Date: 30th July, 2024
Title: Adding additional inspection and testing site.		
Proposed 1st Ship Date: October 30th, 2024		Estimated Sample Availability: Based on the transfer progress of each part case by case
Change Type:		
Assembly Site	Design	Electrical Specification
Test Site X	Assembly Process	Mechanical Specification
Test Process	Assembly Materials	Packing/Shipping/Labeling
PCN Details		
Description of Change:		
MACOM has identified a second source to inspect and test the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.		
Reason for Change:		
Increase the flexibility and continuity of supply.		
Products Affected:		
See next pages.		
Anticipated impact on Fit, Form, Function:		
Form, Fit and Function unaffected.		
Changes to product identification resulting from this PCN:		
None		

Appendix I
Affected part numbers.

No	Model
1	MSS20-146-B10D
2	M4X1964
3	MPN1000-12
4	M3X6185
5	MSS30-142-B10B
6	MX40017-12
7	MMDB30-B11
8	MBC50-0_2B14
9	MBC50-4B12
10	MBC50-3B12
11	M2X8110
12	MSS30-148-B10B
13	MSS30-154-B10B