

MACOM
100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



August 26th, 2024

Richardson RFPD, Inc.
1950 S. Batavia Ave, Suite 100
Geneva, Illinois 60134

ATTN: Quality/Purchasing Manager

PCN-01755

Subject: Adding additional assembly site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly site for the parts listed in the next pages.

In addition to our current sites, we plan to assemble these parts at our long-standing Contract Manufacturer Unisem, in Malaysia. Unisem is a valued, high-quality manufacturing partner for many MACOM products. .

After the change, the datasheet specifications will remain unchanged. MACOM will perform full package qualification for the part to the relevant JEDEC standards. The qualification report, customer samples should be available by January,2025. Deliveries of this part, in January,2025 will be expected from the new assembly location.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely,

Eng Wah Woo
Package & Process Development Manager
EngWah.Woo@macom.com

PCN Number: PCN-01755		PCN Date: August 26th, 2024
Title: Adding additional assembly site.		
Proposed 1st Ship Date: January, 2025		Estimated Sample Availability: January, 2025
Change Type:		
Assembly Site X	Design	Electrical Specification
Test Site	Assembly Process	Mechanical Specification
Test Process	Assembly Materials	Packing/Shipping/Labeling
PCN Details		
Description of Change:		
MACOM has identified a second source to assemble the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.		
Reason for Change:		
Increase the flexibility and continuity of supply.		
Products Affected:		
See next page.		
Anticipated impact on Fit, Form, Function:		
Form, Fit and Function unaffected.		
Changes to product identification resulting from this PCN:		
None		

Appendix I
Affected part numbers

Part Number	QBS Vehicle
CMPA2735015S	Qualification part
CMPA0530002S	CMPA2735015S
CMPA851A005S	CMPA2735015S
CMPA851A012S	CMPA2735015S
CMPA5259050S	Qualification part
CMPA2735030S	CMPA5259050S
CMPA5259025S	CMPA5259050S
CMPA2935250S	Qualification part
CMPA5259050S1	CMPA2935250S
CMPA851A025S	CMPA2935250S
CMPA9396025S	CMPA2935250S
APCM901A030P	CMPA2935250S
CMPA901A020S	CMPA2935250S
CMPA801B030S	CMPA2935250S
APCM801B030S	CMPA2935250S
CMPA851A050S	CMPA2935250S
CMPA5259080S	CMPA2935250S
CMPA2935150S	CMPA2935250S
CMPA5259100S	CMPA2935250S
CGHV27060MP/SA	Qualification part
CGHV35060MP/SA	CGHV27060MP/SA