

MACOM
100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



October 24th, 2024

Richardson RFPD, Inc.
2001 Butterfield Road, Suite 1800
Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

PCN-01787

Subject: Adding additional assembly and testing site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly and testing site for the parts listed in the next pages.

In addition to our current sites, we plan to assemble and test these parts based on the requirement at our long-standing Contract Manufacturer, Hana Semiconductor Co. Ltd, in Ayutthaya, Thailand. Hana is a valued, high-quality manufacturing partner for many MACOM products. After the change, the datasheet specifications will remain unchanged. The qualification report for the representative part is upon request.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely,

Paul Wade
Senior Product Marketing Manager
paul.wade@macom.com

PCN Number: PCN-01787		PCN Date: October 24th, 2024
Title: Adding additional assembly and testing site.		
Proposed 1st Ship Date: January 24th, 2025		Estimated Sample Availability: Sample's availability based on the transfer progress of each part case by case
Change Type:		
Assembly Site X	Design	Electrical Specification
Test Site X	Assembly Process	Mechanical Specification
Test Process	Assembly Materials	Packing/Shipping/Labeling
PCN Details		
Description of Change:		
MACOM has identified a second source to assemble and test the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.		
Reason for Change:		
Increase the flexibility and continuity of supply.		
Products Affected:		
See next pages.		
Anticipated impact on Fit, Form, Function:		
Form, Fit and Function unaffected.		
Changes to product identification resulting from this PCN:		
None		

Appendix I
Affected part numbers

Part Number	Part type	QBS vehicle
MADP-07006B-NM401T	ODS-401	MADP-07006B-NM401T
MA4P1200-401T	ODS-401	MADP-07006B-NM401T
MA4P4002B-402	ODS-402	MADP-07006B-NM401T
MA4PH253	ODS-402	MADP-07006B-NM401T
MA4P929-401	ODS-401	MADP-07006B-NM401T
DP-007006-040100	ODS-401	MADP-07006B-NM401T
MA4P1200-401	ODS-401	MADP-07006B-NM401T
MA4P1200NM-401T	ODS-401	MADP-07006B-NM401T
MA4P7002B-401T	ODS-401	MADP-07006B-NM401T
MA4P7101B-401	ODS-401	MADP-07006B-NM401T
MA4P7102B-401	ODS-401	MADP-07006B-NM401T
MA4P7104B-401	ODS-401	MADP-07006B-NM401T
MA4P7480NM-401T1	ODS-401	MADP-07006B-NM401T
MA4P930	ODS-401	MADP-07006B-NM401T
MA4PH183	ODS-401	MADP-07006B-NM401T
MA4PH210-401	ODS-401	MADP-07006B-NM401T
MA4PH215	ODS-401	MADP-07006B-NM401T
MA4PH232	ODS-401	MADP-07006B-NM401T
MA4PH279	ODS-401	MADP-07006B-NM401T
MA4PH530	ODS-401	MADP-07006B-NM401T
MA4PH618	ODS-401	MADP-07006B-NM401T
MA4P4001B-402	ODS-402	MADP-07006B-NM401T
MA4P4001BNM-402	ODS-402	MADP-07006B-NM401T
MADP-04002B-NM402T	ODS-402	MADP-07006B-NM401T
MA4P4006B-402	ODS-402	MADP-07006B-NM401T
MA4P4301B-402	ODS-402	MADP-07006B-NM401T
MA4P4302B-402	ODS-402	MADP-07006B-NM401T
MA4P7481NM-402	ODS-402	MADP-07006B-NM401T
MA4P931	ODS-402	MADP-07006B-NM401T
MA4PH110	ODS-402	MADP-07006B-NM401T
MA4PH606	ODS-402	MADP-07006B-NM401T
MA4PH640	ODS-402	MADP-07006B-NM401T
MA4PH650-402	ODS-402	MADP-07006B-NM401T

MA4P929-401	ODS-401	MADP-07006B-NM401T
MA4P929-401T	ODS-401	MADP-07006B-NM401T
MA4PH253	ODS-402	MADP-07006B-NM401T
MA4P4002B-402	ODS-402	MADP-07006B-NM401T