

MACOM

100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



December 02, 2024

Richardson RFPD, Inc.
2001 Butterfield Road, Suite 1800
Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

PCN-01808

Subject: Adding additional assembly and inspection site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly and inspection site for the part listed in the next page.

In addition to our current sites, we plan to assemble and inspect these parts at our long-standing Contract Manufacturer, Hana Semiconductor Co. Ltd, in Ayutthaya, Thailand. Hana is a valued, high-quality manufacturing partner for many MACOM products. After the change, the datasheet specifications will remain unchanged. The qualification data is available upon request.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely,

Paul Wade
Senior Product Marketing Manager
paul.wade@macom.com

PCN Number: PCN-01808		PCN Date: December 02, 2024
Title: Adding additional assembly and inspection site.		
Proposed 1st Ship Date: February 25th, 2025		Estimated Sample Availability: Based on the transfer process case by case
Change Type:		
Assembly Site X	Design	Electrical Specification
Test Site	Assembly Process	Mechanical Specification
Test Process	Assembly Materials	Packing/Shipping/Labeling
PCN Details		
Description of Change:		
MACOM has identified a second source to assemble and inspect the affected part. There is no change to the form, fit, materials, or performance of the device as a result of this change.		
Reason for Change:		
Increase the flexibility and continuity of supply.		
Products Affected:		
<ul style="list-style-type: none"> • MSW2020-202 • MSW2041-204-R • MSW2041-204-T • LM200802-M-A-300-T • LM202402-Q-C-301-W • LM202402-Q-E-301 • LM202802-Q-C-301-T 		
Anticipated impact on Fit, Form, Function:		
Form, Fit and Function unaffected.		
Changes to product identification resulting from this PCN:		
None		