

MACOM

100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



Feb 10, 2025

Richardson RFPD, Inc.
2001 Butterfield Road, Suite 1800
Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

PCN-01830

Subject: Adding additional inspection and packing site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional inspection and packing site for the parts listed in the next pages.

In addition to our current sites, we planned to inspect and pack these parts at our long-standing Contract Manufacturer, Year 2000, Ho Chi Minh City, Vietnam. Year 2000 is a valued, high-quality manufacturing partner for many MACOM products.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely

Tom Galluccio
Director, Product Marketing
thomas.galluccio@macom.com

PCN Number: PCN-01830		PCN Date: FEB 10, 2025
Title: Adding additional inspection and packing site.		
Proposed 1st Ship Date: After April 20 th , 2025		Estimated Sample Availability: Sample's availability based on the transfer progress of each part case by case
Change Type:		
Assembly Site	Design	Electrical Specification
Test Site	Assembly Process	Mechanical Specification
Inspection Site X	Assembly Materials	Packing/Shipping/Labeling
PCN Details		
Description of Change:		
MACOM has identified a second source to inspect and pack the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.		
Reason for Change:		
Increase the flexibility and continuity of supply.		
Products Affected:		
See next pages.		
Anticipated impact on Fit, Form, Function:		
Form, Fit and Function unaffected.		
Changes to product identification resulting from this PCN:		
None		

Appendix I
Affected part numbers

No.	Part number	Part type
1	MA46425-134	Chip
2	MA4BN1840-2	Chip
3	MA4AGFCP910	Chip
4	MA4BN1840-1	Chip
5	MASW-011036-14130G	Chip
6	MA4E2532L-1113	Chip
7	MA4E2513L-1289	Chip
8	MADL-000301-01340W	Chip
9	MAVR-011020-14110G	Chip
10	MA4E2508L-1112	Chip
11	MA4SPS552	Chip
12	MA4E2502L-1246	Chip
13	MA4PC748	Chip
14	MA4AGSW8-1	Chip
15	MADP-017015-13140G	Chip
16	MA4SPS502	Chip
17	MA46477-134	Chip
18	MA4AGC5T3	Chip
19	MADZ-011002-1278G0	Chip
20	MADP-011078-02770W	Chip
21	MADZ-011001-1278G0	Chip
22	MADP-030025-13140G	Chip
23	MA4E1310	Chip
24	MA4E2508M-1112	Chip
25	MA4E2508H-1112	Chip
26	MA4FCP300	Chip
27	MA4FES4TM	Chip
28	MA4AGP3U7T	Chip
29	MA4PC764	Chip
30	MADP-000135-01340W	Chip
31	MADP-000402-12530G	Chip
32	MA4M3150	Chip

33	MASW-011173-DIEW	Chip
34	MASW-006102-13610W	Chip
35	MAVR-011051-DIEWPK	Chip
36	MADS-002501-0002G0	Chip
37	MABT-011000-14230G	Chip
38	MASW-011021-14010W	Chip
39	MADP-042405-130600	Metelic Chip
40	MADP-042505-130600	Metelic Chip
41	MA4SW510	Chip