

MACOM

100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



Partners from RF to Light

December 10, 2025

Richardson RFPD, Inc.
2001 Butterfield Road, Suite 1800
Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

PCN-02023

Subject: Removal of dot brand under stud.

Dear Valued Customer,

The goal of MACOM Technology Solutions is to continually deliver high quality products and services that meet our customers' needs. In accordance with these goals, this communication is to inform you that MACOM is making changes to device MA4P709-150. You are receiving this notice because you have purchased this product in the past two years.

A change in dot branding, remove dot brand under stud from the product. Details of this change are on the following page. Please contact your local sales representative if you have any specific questions.

Sincerely,

Mark McNamara
Senior Product Marketing Manager
mark.mcnamara@macom.com

PCN Number: PCN-02023

PCN Date: December 10, 2025

Title: Removal of dot brand under stud.

Proposed 1st Ship Date:
March, 2026


Estimated Sample Availability:
February, 2026

Change Type:

Assembly Site	Design	Electrical Specification
Test Site	Assembly Process X	Mechanical Specification
Test Process	Assembly Materials	Packing/Shipping/Labeling

PCN Details:

- **Description of Change:**
MACOM is making a change by removing out the dot brand under stud. This dot brand is unnecessary, as the stud is the cathode.



- **Reason for Change:**
To improve the manufacturability and remove unnecessary process.

Products Affected:

MA4P709-150

Anticipated impact on Fit, Form, Function:

Form, Fit, and Function unaffected.

Changes to product identification resulting from this PCN:

None