

MACOM
100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



April 21, 2021

Richardson RFPD, Inc.
1950 S. Batavia Ave, Suite 100
Geneva, Illinois 60134

ATTN: Quality/Purchasing Manager

Subject: Addition of BCB coating – Multiple part numbers

PCN #: PCN-01417

Dear Valued Customer:

The goal of MACOM Technology Solutions is to continually deliver high quality products and services that meet our customers' needs. We strive to offer products that are industry leading in terms of performance, delivery, safety and value.

In accordance with these goals, this communication is to inform you that MACOM is making a change to the following products:

DU28120T	DU2860U	MRF141G	MRF151A
DU28120V	DU2880T	MRF148A	MRF151G
DU28200M	DU2880U	MRF150	MRF154
DU2820S	FH2164	MRF150J	MRF157
DU280SUB	MAPF-011002	MRF150MP	MRF157MP
DU2840S	MRF141	MRF151	MRF428

A benzocyclobutene (BCB) polymer top coat is being added to the top surface of the die. This coat helps protect the active area surface from contamination and physical damage. There are no changes to design, form, fit, function, or reliability associated with this change. This change is effective immediately on Foundry work in process. There may be material in MACOM stock which will not have the BCB. Transition to 100% stock having BCB on above part numbers will occur over the coming months.

Please contact your local sales representative if you have any questions or require additional information.

Sincerely,

Greg French
Product Marketing Director
MACOM
Tel: +1 (949) 231-0282
E-mail: gregory.french@macom.com