

> Customer Product Information (CPI)

Product group:	DRIVERS	Rev.: 0
No.:	PN21-078	05 Nov 2021
	SKYPER 32 Drivers - second source supplier of switching components	

Dear valued partner,
Thank you for using SEMIKRON products. Within our continuous improvement activities we are working to enhance performance, quality and reliability of our products. This notification is to inform you of a minor change, where no acknowledgment is required.

Subject of change: Second source supplier of switching components

SEMIKRON L6100102 SKYPER 32 R
product type: L6100103 SKYPER 32/01 R
L6100104 SKYPER 32 R UL
L6100202 SKYPER 32 PRO R
L5046101 SKYPER 32 2nd edition
L5046102 SKYPER 32 2nd edition CV
L5046104 SKYPER 32 2nd edition (with cover)
L5046105 SKYPER 32 2nd edition CV (with cover)
Description of change: Release of 2nd source supplier of switching components

Reason for change: Improvement of supply chain

Impact of change: No change of fit, form and function.

Identification of change: Date code

Time schedule for change: 11/2021

Qualification:

Test	Result
Functional test	Passed
Thermography	Passed

Supporting documentation:

-

Author: Darmanandana, Adyatmika

Products Affected:

The following table shows the affected products and the last transactions (orders, frame orders or quotations), where available with customer part number, order or quote request reference, product quantity and date of transaction.

Part No.	Variant	Article Description	Successor Part No.	Transaction Type	Customer Reference	Document Date	Quantity	Customer Part No.
L6100102		SKYPER 32 R		Order	113259	04/15/2021	1600	