

Customer Notification of

☒ **PRODUCT-** / ☐ **PROCESS CHANGE**

(According to JEDEC Standard J-STD-046 July 2016)

Vincotech – PCN – No 2025-014

SUBJECT OF CHANGE:	Optimize housing design of <i>flow</i> E1 housing
PRODUCTS AFFECTED:	See list below
REASON OF CHANGE:	Improve robustness of housing
CLASSIFICATION OF CHANGE:	MINOR (only for information, no customer acknowledgement required)

DESCRIPTION OF CHANGE:

SUBJECT	CURRENT	NEW
Mechanical design optimization		Cutout at screwing tab (see image)
		

ANTICIPATED IMPACT ON:

Form:	Yes (Specified package drawing dimensions remain unchanged.)
Fit:	No
Function:	No
Others:	No

TIME SCHEDULE:

Final qualification report:	Accomplished according to standard qualification
First samples available:	According to the standard delivery time
Earliest implementation date:	2025-Aug-04

PRODUCT IDENTIFICATION:

Part#	Current Revision	New Revision
10-EZ07H5A050SM01-M097F18T	n	n+1
10-EZ126PA035SC-L859F48T-/3/	n	n+1
10-EZ12PNA015SC-L928C08T	n	n+1





Part#	Current Revision	New Revision
10-EZ16IRA100RS-LA89J06T	n	n+1
10-EZ074PA023MF-LB39F08T	n	n+1
10-EZ073WA040SM-LD64F08T	n	n+1
10-EZ126PA025SC-L858F48T	n	n+1
10-EZ12PMA015SC-L928A08T	n	n+1
10-EZ12PMA010SC-L927A08T	n	n+1
10-EZ126PA035SC-L859F48T	n	n+1
10-EZ07NIA075S5-LF35F58T	n	n+1
10-EZ07B1A040RG-M045L78T	n	n+1
10-EZ073BB040RG-M086L88T	n	n+1
10-EZ078RA030IH01-LF75J08T	n	n+1
10-EZ12PMA010M7-L927A78T	n	n+1
10-EZ12PMA015M7-L928A78T	n	n+1
10-EZ126PA025M7-L858F78T	n	n+1
10-EZ126PA035M7-L859F78T	n	n+1
10-EZ07H5B080RV-M098F88T	n	n+1
10-EZ12ORA040RO01-LF87J86T	n	n+1
10-EZ12NMA080SH03-L329F58T	n	n+1
10-EZ06PMA030SA-L926A38T	n	n+1
10-EZ06PMA010SA-L923A38T	n	n+1
10-EZ06PMA015SA-L924A38T	n	n+1
10-EZ066PA050SA-L855F38T	n	n+1
10-EZ06PMA020SA-L925A38T	n	n+1
10-EZ12PNA010SC-L927C08T	n	n+1
10-EZ12PNA010M7-L927C78T	n	n+1
10-EZ12PNA015M7-L928C78T	n	n+1
10-EZ066PA050SA-L855F38T-/3/	n	n+1
10-E112PNA010M7-L927C78Z-/3/	n	n+1
10-E112PNA015M7-L928C78Z-/3/	n	n+1
10-E1126PA025M7-L858F78Z	n	n+1
10-EZ12PMA025M7-L929A78T	n	n+1
10-EZ126PA050M7-L850F78T	n	n+1
10-E1066PA050SA-L855F38Z	n	n+1
10-E1126PA035M7-L859F78Z-/3/	n	n+1
10-E1126PA035M7-L859F78Z	n	n+1
10-E112PMA010M7-L927A78Z	n	n+1
10-E112PMA015M7-L928A78Z	n	n+1
10-E1122PA020MM-LN32F08Z-/3/	n	n+1
10-EZ12NMA080SH06-L329F68T	n	n+1
10-EZ074PA041VM01-LG34F28T	n	n+1
10-E1126PA025M7-L858F78Z-/3/	n	n+1
10-EZ07TTA050SM03-LF94D03T	n	n+1
10-E112PNA015M7-L928C78Z	n	n+1





Part#	Current Revision	New Revision
10-E112PMA010M7-L927A78Z-/3/	n	n+1
10-E112PMA015M7-L928A78Z-/3/	n	n+1
10-E112PMA015M7-L928A78Z-/3/	n	n+1
10-EZ124PA020MO-LQ18F08T-/3/	n	n+1
10-EZ124PA032ME-LQ17F18T	n	n+1
10-EZ124PA040MR-LR07F38T	n	n+1
10-EZ124RA010RO-LS06J88T	n	n+1
10-EZ126PB075ME-LS17F08T	n	n+1
10-EZ124PA032ME-LQ17F18T-/3/	n	n+1
10-EZ12NMA080SH50-L329F53T	n	n+1
10-EZ12PMA025M7-L929A78T-/3/	n	n+1
10-EZ174PA100MR-LR06F38T	n	n+1
10-EZ124RA030RO-LS08J88T	n	n+1
10-E1126PA050M7-L850F78Z	n	n+1
10-E112PMA025M7-L929A78Z-/3/	n	n+1
10-EZ17SWA150SA-LU09F38T	n	n+1
10-EZ17SWA150M701-LU09F78T	n	n+1
10-EZ17SRA680RS-LU00J08T	n	n+1
10-EZ17SRA560JR-LU00J18T	n	n+1
10-EZ06O3A015IH01-LR13J18T	n	n+1
10-E112PMA025M7-L929A78Z	n	n+1
10-EZ126TA025SC-L858F43T	n	n+1
10-E107PSA015M7-LU74A08Z-/3/	n	n+1
10-E112PSA010M7-LU77A08Z-/3/	n	n+1
10-E112PNA010M7-L927C78Z	n	n+1
10-E106PPA006SB-LV12B28Z-/3/	n	n+1
10-EZ126PA025M7-L858F78T-/3/	n	n+1
10-EZ174RA018RO-LS07J83T	n	n+1
10-EZ122PA016ME-LJ67F68T-/3/	n	n+1
10-EZ174PA050MR-LR07F33T	n	n+1
10-EZ124PA018MR-LR09F08T	n	n+1
10-EZ124PA016ME-LQ18F18T-/3/	n	n+1
10-EZ07NIA075RG-LF35F68T	n	n+1
10-EZ122PA016ME-LJ67F68T	n	n+1
10-EZ082PA023MR-PC62L08T	n	n+1
10-EZ072PA023ME-PC62L18T	n	n+1
10-EZ124RA030RO-LS08J88T-/3/	n	n+1
10-E106PMA030SA-L926A38Z	n	n+1
10-EZ122PB032ME-PE07F18T-/7/	n	n+1
10-EZ124PA016ME-LQ18F18T	n	n+1
10-EZ124PA011MR-LR00F08T	n	n+1
10-EZ07O2B040RO-PF53J48T	n	n+1
10-EZ174RA025RO-LS08J83T	n	n+1





Part#	Current Revision	New Revision
10-EZ12B1A080N305-LT09L42T	n	n+1
10-EZ122PB032ME-PE07F18T	n	n+1
10-E1122PA100M7-PG68F78Z	n	n+1
10-EZ074PB075SM-PH28F58T	n	n+1
10-EZ123BA036MR-PH39L08T	n	n+1
10-E107B2A045ME01-LK65L68Z	n	n+1
10-E107B2A045ME02-LK65L63Z	n	n+1
10-E107B2A060SM01-LK65L58Z	n	n+1
10-E107B2A060SM02-LK65L53Z	n	n+1
10-E112PMA015M701-L928A73Z-/3/	n	n+1
10-E107B2A045ME01-LK65L68Z-/7/	n	n+1
10-EZ12B2A036MR-PH39L03T	n	n+1
10-EZ124PC016ME-PK28F18T-/7/	n	n+1
10-EZ126PA015M7-L857F78T	n	n+1
10-EZ126PB075ME-LS17F08T-/7/	n	n+1
10-EZ126PB032ME-LS18F08T-/7/	n	n+1
10-E112PNA015M7-L928C78Z-/7/	n	n+1
10-E106PMA020SA-L925A38Z	n	n+1
10-EZ123BA036MR-PH39L08T-/3/	n	n+1
10-EZ126PA080MS-LS17F78T	n	n+1
10-EZ126PB030MS-LS18F78T	n	n+1
10-EZ124PA060MS-LQ16F78T	n	n+1
10-EZ124PA030MS-LQ17F78T	n	n+1
10-EZ126PB032ME-LS18F08T	n	n+1
10-EZ122PC100M7-PL39F78T	n	n+1
10-EZ122PC050M7-PL37F78T	n	n+1
10-E112PMA015M701-L928A73Z	n	n+1
10-E1074PA023ME01-LQ12F68Z	n	n+1
10-E1074PA023ME02-LQ12F66Z	n	n+1
10-E1074PA023ME03-LQ12F64Z	n	n+1
10-E1074PA015ME01-LQ13F68Z	n	n+1
10-E1074PA015ME02-LQ13F66Z	n	n+1
10-E1074PA015ME03-LQ13F64Z	n	n+1
10-EZ06PMA020SA-L925A38T-/3/	n	n+1
10-EZ06PMA010SA-L923A38T-/3/	n	n+1
10-EZ06PMA030SA-L926A38T-/3/	n	n+1
10-E106L3A060P7-PM32L78Z-/7/	n	n+1
10-E107L3A045ME-PM33L18Z-/7/	n	n+1
10-EZ124PA040MS01-LQ17F73T-/3/	n	n+1
10-EZ12B2A040MS-LQ17L73T-/3/	n	n+1
10-EZ12B2A032ME-LQ17L18T-/3/	n	n+1
10-E107PMA020I7-L925A28Z	n	n+1
10-E107PMA030I7-L926A28Z	n	n+1





Vincotech

Part#	Current Revision	New Revision
10-E112PNA025M7-L929C78Z-/7/	n	n+1
10-EZ07PPB020I701-PM84A08T	n	n+1
10-E106PMA030SA-L926A38Z-/7/	n	n+1
10-EZ126PB040MS01-LS18F73T	n	n+1
10-EZ12B2A036MR-PH39L03T-/7/	n	n+1
10-EZ123BA036MR-PH39L08T-/7/	n	n+1
10-EZ07NBA75S5-PN28L58T	n	n+1
10-E1126PA035M7-L859F78Z-/7/	n	n+1
10-E1126PA025M7-L858F78Z-/7/	n	n+1
10-EZ126TA025M7-L858F73T	n	n+1
10-E1074PD015ME-PN44F68Z-/7/	n	n+1
10-EZ126PA035SC-L859F48T-/7/	n	n+1
10-EZ126PA035M7-L859F78T-/7/	n	n+1
10-EZ122PA011ME-LJ67F18T	n	n+1
10-EZ126PB040MS01-LS18F73T-/7/	n	n+1
10-E1082PA023MR-LN32F98Z-/3/	n	n+1
10-E112PMA015M7-L928A78Z-/7/	n	n+1
10-E1066PA050SA-L855F38Z-/7/	n	n+1
10-EZ122PC100M7-PL39F78T-/7/	n	n+1

Important information for your attention:

Minor change:

- For information purpose only (no customer acknowledgement required)

Major change:

- Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN.
- Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change.
- After acknowledgement, lack of additional response within the 90 days period constitutes acceptance of the change.

Vincotech Contact:

Web: www.vincotech.com

Email: PCN_Support@vincotech.com

