

Customer Notification of PRODUCT-DISCONTINUATION

(According to JEDEC Standard J-STD-048 Nov 2014)

Vincotech – PD – No 2024-016

PRODUCTS AFFECTED:	See list below
REASON:	Component discontinuation

TIME SCHEDULE:

Last order:	2025-04-01
Last delivery:	2026-04-01

PRODUCT IDENTIFICATION:

Discontinued product	Product replacement
10-PZ126PA080ME-M909F18Y	10-PZ126PA075ME-M909F38Y
10-PC094PB065ME01-L637F06Y-/3/	10-PC124PA032ME-L638F98Y-/7/
10-PC094PB035ME02-L629F36Y	10-PZ124PA032ME03-L629F98Y
10-PC094PB017ME02-L620F36Y	Replacement upon request
10-PC094PB017ME02-L620F36Y-/3/	Replacement upon request
10-PC094PB065ME01-L637F06Y	10-PC124PA032ME-L638F98Y
10-PG123BA080SH01-LN68L38T	10-PG123BA080SH11-LN68L33T
10-FU094PB017ME05-L620F31	Replacement upon request
B0-SP10S3A100S7-LR69L08T-/7/	B0-SP10S3A100S710-LR69L03T-/7/
B0-SP103BA100S714-LS60L98T-/7/	B0-SP103BB100S764-PB80L98T-/7/
10-PZ126PA080ME-M909F18Y-/3/	10-PZ126PA075ME-M909F38Y-/7/
B0-SL10NIB600S702-PA29F78Z-/7/	B0-SL10NIB600S701-PA29F48Z-/7/
B0-SL10NIC600S702-PA39F78Z-/7/	B0-SL10NIC600S701-PA39F48Z-/7/
B0-SL10B2A200S704-PA58L98Z-/7/	B0-SL10B2A200S705-PA58L96Z-/7/
10-FZ06B2A060P7-PB53L78	10-FZ06B2A060P701-PB53L73
B0-SP10B2A200S704-PA58L98T-/7/	B0-SP10B2A200S705-PA58L96T-/7/
B0-SL10NIB600S704-PB69F78Z-/7/	Replacement upon request
B0-SL10NIC600S704-PB79F78Z-/7/	Replacement upon request
10-FU094PB017ME02-L620F36	Replacement upon request
B0-SL103BB100S714-PB80L93Z-/7/	B0-SL103BB100S764-PB80L98Z-/7/
B0-SP103BB100S714-PB80L93T-/7/	B0-SP103BB100S764-PB80L98T-/7/
B0-SL103BB100S714-PB80L93Z	B0-SL103BB100S764-PB80L98Z

Vincotech Contact:

Web: www.vincotech.com

Email: PCN_Support@vincotech.com