



Product/Process Change Notice - PCN 24_0009 Rev. H

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887, USA

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. An acceptance or concern response should be submitted to ADI promptly. Any requests for samples of changed material or additional information must be made within 30 days of the notification. In accordance with JEDEC Standard 046, customers should acknowledge receipt of the PCN within 30 days of the PCN delivery. ADI contact information is listed below. Note: Revised fields are indicated by a red field name. See Appendix B for revision history.

Lack of acknowledgment of the PCN within 30 days constitutes acceptance of the change. After the acknowledgment, a lack of additional requests within 90 days constitutes acceptance of the change.

Note: Revised fields are indicated by a red field name. See Appendix B for revision history.

PCN Title:	Qualification of Alternative Wafer Fab for TSMC 0.18um Mixed Signal CMOS Process
Publication Date:	07-Jan-2026
Effectivity Date:	18-Dec-2025 <i>(the earliest date that a customer could expect to receive changed material)</i>
Revision Description:	Minor correction to the PCN description for improved accuracy.

Description Of Change:

Analog Device is qualifying Analog Devices Beaverton OR, USA (ADBN) as an alternate Wafer Fab site for 0.18um Mixed Signal CMOS Process.

Reason For Change:

This change will ensure manufacturing agility and continuity of supply.

Impact of the change (positive or negative) on fit, form, function & reliability:

There is no impact to form, fit, function or reliability.

Product Identification: *(this section will describe how to identify the changed material)*

ADI maintains traceability internally to manufacturing location site via marking on the device.

Summary of Supporting Information:

Qualification has been performed per Industry Standard Test Methods. See attached Qualification Results.

Supporting Documents:

Attachment 1: Type: Delta Qualification Matrix

ADI_PCN_24_0009_Rev_H_PCN-Delta-Qualification-Matrix-ZVEI-5_0_16 Correction May2024.xlsm

Attachment 2: Type: Qualification Results Summary

ADI_PCN_24_0009_Rev_H_Qualification Results 018umMixed Mode.pdf

Note: If applicable, the device material declaration will be updated due to material change.

ADI Contact Information:

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas:	Europe:	Japan:	Korea:	Rest of Asia:
PCN_Americas@analog.com	PCN_Europe@analog.com	PCN_Japan@analog.com	PCN_Korea@analog.com	PCN_ROA@analog.com

Appendix A - Affected ADI Models:

Existing Parts - Product Family / Model Number (198)

AD8283 / AD8283WBCPZ	AD8283 / AD8283WBCPZ-RL	AD8285 / AD8285WBCPZ	AD8285 / AD8285WBCPZ-RL	AD9212 / AD9212ABCPZ-40
AD9212 / AD9212ABCPZ-65	AD9222 / AD80418BCPZ-65	AD9222 / AD9222ABCPZ-40	AD9222 / AD9222ABCPZ-50	AD9222 / AD9222ABCPZ-65
AD9222 / AD9222ABCPZRL7-50	AD9249 / AD9249BBCZ-65	AD9249 / AD9249BBCZRL7-65	AD9252 / AD9252ABCPZ-50	AD9252 / AD9252ABCPZRL7-105
AD9253 / AD9253BCPZ-105	AD9253 / AD9253BCPZ-125	AD9253 / AD9253BCPZ-80	AD9253 / AD9253BCPZRL7-105	AD9253 / AD9253BCPZRL7-125
AD9253 / AD9253BCPZRL7-80	AD9253 / AD9253TCPZ-125EP	AD9253 / AD9253TCPZRL7-125EP	AD9255 / AD9255BCPZ-105	AD9255 / AD9255BCPZ-125
AD9255 / AD9255BCPZ-80	AD9255 / AD9255BCPZRL7-105	AD9255 / AD9255BCPZRL7-125	AD9255 / AD9255BCPZRL7-80	AD9257 / AD9257BCPZ-40
AD9257 / AD9257BCPZ-65	AD9257 / AD9257BCPZRL7-40	AD9257 / AD9257BCPZRL7-65	AD9257 / AD9257TCPZ-65-EP	AD9257S / AD9257TCPZ-65-CSL
AD9265 / AD89025BCPZ	AD9265 / AD89025BCPZRL7	AD9265 / AD9265BCPZ-105	AD9265 / AD9265BCPZ-125	AD9265 / AD9265BCPZ-80
AD9265 / AD9265BCPZRL7-105	AD9265 / AD9265BCPZRL7-125	AD9265 / AD9265BCPZRL7-80	AD9608 / AD9608BCPZ-105	AD9608 / AD9608BCPZ-125
AD9608 / AD9608BCPZRL7-105	AD9608 / AD9608BCPZRL7-125	AD9609 / AD9609BCPZ-20	AD9609 / AD9609BCPZ-40	AD9609 / AD9609BCPZ-65
AD9609 / AD9609BCPZ-80	AD9609 / AD9609BCPZRL7-20	AD9609 / AD9609BCPZRL7-40	AD9609 / AD9609BCPZRL7-65	AD9609 / AD9609BCPZRL7-80
AD9628 / AD9628BCPZ-105	AD9628 / AD9628BCPZ-125	AD9628 / AD9628BCPZRL7-105	AD9628 / AD9628BCPZRL7-125	AD9629 / AD9629BCPZ-20
AD9629 / AD9629BCPZ-40	AD9629 / AD9629BCPZ-65	AD9629 / AD9629BCPZ-80	AD9629 / AD9629BCPZRL7-20	AD9629 / AD9629BCPZRL7-40
AD9629 / AD9629BCPZRL7-65	AD9629 / AD9629BCPZRL7-80	AD9633 / AD9633BCPZ-105	AD9633 / AD9633BCPZ-125	AD9633 / AD9633BCPZ-80
AD9633 / AD9633BCPZRL7-105	AD9633 / AD9633BCPZRL7-125	AD9633 / AD9633BCPZRL7-80	AD9635 / AD9635BCPZ-125	AD9635 / AD9635BCPZ-80
AD9635 / AD9635BCPZRL7-125	AD9635 / AD9635BCPZRL7-80	AD9637 / AD9637BCPZ-40	AD9637 / AD9637BCPZ-80	AD9637 / AD9637BCPZRL7-40
AD9637 / AD9637BCPZRL7-80	AD9645 / AD9645BCPZ-125	AD9645 / AD9645BCPZ-80	AD9645 / AD9645BCPZRL7-125	AD9645 / AD9645BCPZRL7-80
AD9645 / AD9645WBCPZ-80	AD9645 / AD9645WBCPZRL7-80	AD9648 / AD9648BCPZ-105	AD9648 / AD9648BCPZ-125	AD9648 / AD9648BCPZRL7-105
AD9648 / AD9648BCPZRL7-125	AD9648 / AD9648TCPZ-125-EP	AD9648 / AD9648TCPZ125EPRL7	AD9649 / AD9649BCPZ-20	AD9649 / AD9649BCPZ-40
AD9649 / AD9649BCPZ-65	AD9649 / AD9649BCPZ-80	AD9649 / AD9649BCPZRL7-20	AD9649 / AD9649BCPZRL7-40	AD9649 / AD9649BCPZRL7-65
AD9649 / AD9649BCPZRL7-80	AD9681 / AD9681BBCZ-125	AD9681 / AD9681BBCZRL7-125	AD9704 / AD9704BCPZ	AD9704 / AD9704BCPZRL7
AD9705 / AD9705BCPZ	AD9705 / AD9705BCPZRL7	AD9706 / AD9706BCPZ	AD9706 / AD9706BCPZRL7	AD9707 / AD9707BCPZ
AD9707 / AD9707BCPZRL7	AD9714 / AD9714BCPZ	AD9714 / AD9714BCPZRL7	AD9715 / AD9715BCPZ	AD9715 / AD9715BCPZRL7
AD9716 / AD9716BCPZ	AD9716 / AD9716BCPZRL7	AD9717 / AD9717BCPZ	AD9717 / AD9717BCPZRL7	AD9911 / AD9911BCPZ
AD9911 / AD9911BCPZ-REEL7	AD9958 / AD9958BCPZ	AD9958 / AD9958BCPZ-REEL7	AD9959 / AD9959BCPZ	AD9959 / AD9959BCPZ-REEL7
ADA4355 / ADA4355ABCZ	ADA8282 / ADA8282WBCPZ	ADA8282 / ADA8282WBCPZ-R7	ADAR7251 / ADAR7251WBCSZ	ADAR7251 / ADAR7251WBCSZ-RL
ADAU1361 / ADAU1361BCPZ	ADAU1361 / ADAU1361BCPZ-R7	ADAU1361 / ADAU1361BCPZ-RL	ADAU1401 / AD71073YSTZ-RL	ADAU1401 / ADAU1401YSTZ
ADAU1401 / ADAU1401YSTZ-RL	ADAU1701 / ADAU1701JSTZ	ADAU1701 / ADAU1701JSTZ-RL	ADAU1702 / ADAU1702JSTZ	ADAU1702 / ADAU1702JSTZ-RL
ADCLK846 / ADCLK846BCPZ	ADCLK846 / ADCLK846BCPZ-REEL7	ADCLK854 / ADCLK854BCPZ	ADCLK854 / ADCLK854BCPZ-REEL7	ADDR9501 / ADDR9501BCPZ
ADDR9501 / ADDR9501BCPZRL	ADDR9501 / ADW15001YCPZ	ADDR9501 / ADW15001YCPZRL	ADE9000 / ADE9000ACPZ	ADE9000 / ADE9000ACPZ-RL
ADE9000A / ADE9000AACPZ	ADE9000A / ADE9000AACPZ-RL	ADE9039 / ADE9039ACPZ	ADE9039 / ADE9039ACPZ-RL	ADE9078 / ADE9078ACPZ
ADE9078 / ADE9078ACPZ-RL	ADE9153A / ADE9153AACPZ	ADE9153A / ADE9153AACPZ-RL	ADE9153B / ADE9153BACPZ	ADE9153B / ADE9153BACPZ-RL
ADE9430 / ADE9430ACPZ	ADE9430 / ADE9430ACPZ-RL	ADF7023 / AD57005Z-0RL	ADF7023 / ADF7023BCPZ	ADF7023 / ADF7023BCPZ-RL
ADF7023-J / ADF7023-JBCPZ	ADF7023-J / ADF7023-JBCPZ-RL	ADF7024 / ADF7024BCPZ	ADF7024 / ADF7024BCPZ-RL	ADV7180 / ADV7180BCPZ
ADV7180 / ADV7180BCPZ-REEL	ADV7180 / ADV7180WBCPZ	ADV7180 / ADV7180WBCPZ-REEL	ADV7340 / ADV7340BSTZ	ADV7341 / ADV7341BSTZ
ADV7342 / ADV7342BSTZ	ADV7343 / ADV7343BSTZ	ADV7343 / ADV7343WBSTZ	ADV7343 / ADV7343WBSTZ-RL	ADV7344 / ADV7344BSTZ
ADV7390 / ADV7390BCBZ-A-RL	ADV7390 / ADV7390BCPZ	ADV7390 / ADV7390BCPZ-REEL	ADV7390 / ADV7390WBCPZ	ADV7390 / ADV7390WBCPZ-RL
ADV7391 / ADV7391BCPZ	ADV7391 / ADV7391BCPZ-REEL	ADV7391 / ADV7391WBCPZ	ADV7391 / ADV7391WBCPZ-RL	ADV7392 / ADV7392BCPZ
ADV7392 / ADV7392BCPZ-3REEL	ADV7392 / ADV7392BCPZ-REEL	ADV7392 / ADV7392WBCPZ	ADV7392 / ADV7392WBCPZ-REEL	ADV7393 / ADV7393BCPZ
ADV7393 / ADV7393BCPZ-REEL	ADV7393 / ADV7393WBCPZ	ADV7393 / ADV7393WBCPZ-REEL		

Appendix A - Affected ADI Models::

Removed Parts On All Revisions - Product Family / Model Number (26)

ADAU1761 / ADAU1761BCPZ	ADAU1761 / ADAU1761BCPZ-R7	ADAU1761 / ADAU1761BCPZ-RL	ADV7180 / ADV7180BCP32Z	ADV7180 / ADV7180BCP32Z-RL
ADV7180 / ADV7180BST48Z	ADV7180 / ADV7180BST48Z-RL	ADV7180 / ADV7180BSTZ	ADV7180 / ADV7180BSTZ-REEL	ADV7180 / ADV7180KCP32Z
ADV7180 / ADV7180KCP32Z-RL	ADV7180 / ADV7180KST48Z	ADV7180 / ADV7180KST48Z-RL	ADV7180 / ADV7180WBCP32Z	ADV7180 / ADV7180WBCP32Z-RL
ADV7180 / ADV7180WBST48Z	ADV7180 / ADV7180WBST48Z-RL	ADV7180 / ADV7180WBSTZ	ADV7180 / ADV7180WBSTZ-REEL	ADV7180 / ADW10003-0REEL
ADV7180 / ADW10004-0REEL	ADV7180 / ADW10006Z-0	ADV7180 / ADW10007Z-0REEL	ADV7180 / ADW10008Z-0REEL	ADV7180 / ADW10013Z-0
ADV7180 / ADW10013Z-0RL				

Appendix B - Revision History:

Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	01-Feb-2024	05-May-2024	Initial Release.
Rev. A	01-May-2024	03-Aug-2024	Add Parts. Adding completed qualification report.
Rev. B	13-May-2024	15-Aug-2024	Correction to Delta Qualification Matrix. Add parts. Remove parts.
Rev. C	16-Dec-2024	20-Mar-2025	Remove parts. Add updated Qualification Results.
Rev. D	14-Feb-2025	19-May-2025	Remove part.
Rev. E	03-Jul-2025	05-Oct-2025	Add parts. Qualification Report updated from Rev C. to Rev D.
Rev. F	15-Sep-2025	18-Dec-2025	Add parts.
Rev. G	10-Oct-2025	18-Dec-2025	Remove parts.
Rev. H	07-Jan-2026	18-Dec-2025	Minor correction to the PCN description for improved accuracy.