



## Product Discontinuance Notice - PDN 24\_0120 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

### PDN Title:

Discontinuance of DC1073A

**Publication Date:** 18-Dec-2024

**Last Time Buy Date:** 20-Dec-2024

**Last Time Ship Date:** 23-Dec-2024

### Revision Description:

Initial Release.

### Reason For Discontinuance

The BU made a decision to not support this eval board going forward. The recommended replacement model is DC1619A.

### Comments

The recommended replacement model is DC1619A.

**Supporting Documents**      None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

<b>Americas:</b>	PDN_Americas@analog.com	<b>Europe:</b>	PDN_Europe@analog.com	<b>Japan:</b>	PDN_Japan@analog.com
				<b>Rest of Asia:</b>	PDN_ROA@analog.com

### PDN 24\_0120 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
DC1073A	LT3845	DC1619A	No	Order replacement model

### Appendix A - PDN 24\_0120 Revision History

Rev	Publish Date	Rev Description
Rev. -	18-Dec-2024	Initial Release.

Analog Devices, Inc. Proprietary Information

DocId:3199    Layout Rev:4    Parent DocId:None