

QMA




FIG. 4
QMA-TOOL

PART #	FIG	DESCRIPTION	CBL GRP	NOTES	PLATING			RECOMMENDED TOOL
					BDY	P/C	DIE	
RQA-5000-C	1	QMA PLUG, CRIMP (SNAP LOCK)	C, C2		WB	G	T	RFA-4009-206
RQA-5000-C1	1	QMA PLUG, CRIMP (SNAP LOCK)	C1		WB	G	T	RFA-4009-206
RQA-5000-X	1	QMA PLUG, CRIMP (SNAP LOCK)	X		WB	G	T	RFA-4005-100
RQA-5010-8X	2	QMA RIGHT-ANGLE PLUG, CRIMP (SNAP LOCK)	X	SOLDERLESS CONTACT, INCLUDES HEAT SHRINK	WB	G	T	RFA-4009-203
RQA-5010-C	3	QMA RIGHT-ANGLE PLUG, CRIMP (SNAP LOCK)	C, C2		WB	G	T	RFA-4009-206
RQA-5010-C1	3	QMA RIGHT-ANGLE PLUG, CRIMP (SNAP LOCK)	C1		WB	G	T	RFA-4009-206
RQA-5010-X	3	QMA RIGHT-ANGLE PLUG, CRIMP (SNAP LOCK)	X		WB	G	T	RFA-4009-203
QMA-TOOL	4	ASSEMBLY TOOL FOR PRESSING CAP ON RIGHT ANGLE PLUG			SST	—	—	