

Product change note

Topic LILY-W131-00B, LILY-W132-00B product change notification
UBX-22005731 C2-Restricted

Author Sebastian Schreiber

Date 18 March 2022

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com. Copyright© u-blox AG.

1 Affected products

Product name	Ordering code	Old type number	New type number
LILY-W131	LILY-W131-00B	LILY-W131-00B-00	LILY-W131-00B-01
LILY-W132	LILY-W132-00B	LILY-W132-00B-00	LILY-W132-00B-01

Table 1: Affected products

2 Type

- | | |
|---|--|
| <input type="checkbox"/> Product status change | <input checked="" type="checkbox"/> Documentation update |
| <input checked="" type="checkbox"/> Hardware/component change | <input type="checkbox"/> Certification information |
| <input type="checkbox"/> Firmware/software update | <input type="checkbox"/> Security advisory |
| <input checked="" type="checkbox"/> Label change | <input type="checkbox"/> Other |

3 Description

The hardware component change is that two capacitors were replaced, the same as was done in the LILY-W131-10B and LIL-W132-10B variants.

4 Reason for the change

The new components allow three soldering-reflow cycles. (The first cycle is used in the production of the modules, and the two other cycles can be used by customers.)

5 Certification

FCC, ISED and RED: no impact.

Certifications of LILY-W13x-00B remain applicable. No action required by customers.

6 Schedule

Samples	Dates
First shipment date:	01.05.2022
Estimated documentation (e.g., datasheet, release note)	01.05.2022
Estimated last shipment date (for old type number)	31.10.2022

7 Customer impact and recommended action

The type number extension on the product label changes to **00B-01**. Notify visual inspection, if applicable.

8 Related documentation

- [1] LILY-W1 data sheet, [UBX-15000203](#)
- [2] LILY-W1 series system integration manual, [UBX-15027600](#)