

MACOM
100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



December 10, 2024

Richardson RFPD, Inc.
2001 Butterfield Road, Suite 1800
Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

PCN #: PCN-01802

Subject: Adding additional testing site- MAAD-011036

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional inspection and testing site for the parts listed below.

In addition to our current site, we plan to test these parts at our MACOM facility in Hsinchu, Taiwan.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

MAAD-011036
MAAD-011036-TR0500

This change is effective immediately.

Please contact your local sales representative if you have any specific questions.

Sincerely

Alan Miller
Manager-Product Marketing
Email: alan.miller@macom.com