MACOM

100 Chelmsford Street Lowell, MA 01851 +1 978.656.2500

www.macom.com



November 28th, 2024

Richardson RFPD, Inc. 2001 Butterfield Road, Suite 1800 Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

#### **PCN-01810**

Subject: Adding additional assembly site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly site for the parts listed in the next pages.

In addition to our current sites, we plan to assemble these parts at our long-standing Contract Manufacturer Unisem, in Malaysia. Unisem is a valued, high-quality manufacturing partner for many MACOM products.

After the change, the datasheet specifications will remain unchanged. MACOM will perform full package qualification for the part to the relevant JEDEC standards. The qualification report, customer samples should be available by April,2025. Deliveries of this part, in April,2025 will be expected from the new assembly location.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely,

Eng Wah Woo
Package & Process Development Manager
EngWah.Woo@macom.com

PCN Number: PCN-01810 PCN Date: November 28th, 2024

Title: Adding additional assembly site.

Proposed 1st Ship Date: Estimated Sample Availability:

In April, 2025 In April, 2025

**Change Type:** 

Assembly Site X Design Electrical Specification

Test Site Assembly Process Mechanical Specification

Test Process Assembly Materials Packing/Shipping/Labeling

## **PCN Details**

# **Description of Change:**

MACOM has identified a second source to assemble the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.

# **Reason for Change:**

Increase the flexibility and continuity of supply.

#### **Products Affected:**

See next page.

## Anticipated impact on Fit, Form, Function:

Form, Fit and Function unaffected.

# Changes to product identification resulting from this PCN:

None



# Appendix I Affected part numbers

Part Number	QBS Vehicle
WSA5080S	CMPA2735015S
APCM90100L9C	CMPA5259050S
CMPA0560008S	CMPA5259050S
CMPA1F1H060S	CMPA2935250S