

**MACOM**  
100 Chelmsford Street  
Lowell, MA 01851  
+1 978.656.2500  
  
www.macom.com



February 11th, 2025

Richardson RFPD

ATTN: Quality/Purchasing Manager

**PCN-01841**

**Subject: Adding additional assembly site.**

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly site for the parts listed in the next pages.

In addition to our current sites, we plan to assemble these parts at our long-standing Contract Manufacturer Carsem, in Malaysia. Carsem is a valued, high-quality manufacturing partner for many MACOM products.

After the change, the datasheet specifications will remain unchanged. Qualification data will be available upon request. Customer samples should be available by April, 2025. Deliveries of this part from the new assembly location, will begin from April, 2025 based on customer demand. .

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely,

Eng Wah Woo  
Package & Process Development Manager  
[EngWah.Woo@macom.com](mailto:EngWah.Woo@macom.com)

<b>PCN Number:</b> PCN-01841		<b>PCN Date:</b> February 11th, 2025
<b>Title:</b> Adding additional assembly site.		
<b>Proposed 1st Ship Date:</b> In April, 2025		<b>Estimated Sample Availability:</b> In April, 2025
<b>Change Type:</b>		
Assembly Site X	Design	Electrical Specification
Test Site	Assembly Process	Mechanical Specification
Test Process	Assembly Materials	Packing/Shipping/Labeling
<b>PCN Details</b>		
<b>Description of Change:</b>		
MACOM has identified a second source to assemble the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.		
<b>Reason for Change:</b>		
Increase the flexibility and continuity of supply.		
<b>Products Affected:</b>		
<ul style="list-style-type: none"> <li>• CMPA0530002S</li> </ul>		
<b>Anticipated impact on Fit, Form, Function:</b>		
Form, Fit and Function unaffected.		
<b>Changes to product identification resulting from this PCN:</b>		
None		

***Appendix I***  
Affected part numbers

Part Number	QBS Vehicle
CMPA0530002S	CGHV1F025S