MACOM 100 Chelmsford Street

Lowell, MA 01851 +1 978.656.2500

www.macom.com



March 6th, 2025

Richardson RFPD, Inc. 2001 Butterfield Road, Suite 1800 Downers Grove. Illinois 60515

ATTN: Quality/Purchasing Manager

PCN-01853

Subject: Adding additional assembly site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly site for the part listed in the next pages.

In addition to our current sites, we plan to assemble this part at our long-standing Contract Manufacturer, Hana Semiconductor Co. Ltd, in Ayutthaya, Thailand. Hana is a valued, high-quality manufacturing partner for many MACOM products. After the change, the datasheet specifications will remain unchanged. The qualification report will be ready for request after May 31st,2025.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely,

Paul Wade Senior Product Marketing Manager paul.wade@macom.com

| PCN Number: PCN-01853 | | PCN Date: March 6th, 2025 |
|--|--|--|
| Title: Adding additional asse | mbly site. | |
| Proposed 1st Ship Date: | | Estimated Sample Availability: |
| June 6th, 2025 | | May 31st,2025 |
| Change Type: | | |
| Assembly Site X | Design | Electrical Specification |
| Test Site | Assembly Process | Mechanical Specification |
| Test Process | Assembly Materials | Packing/Shipping/Labeling |
| PCN Details | | |
| Description of Change: | | |
| MACOM has identified a se materials,or performance of | cond source to assemble the the device as a result of this cha | affected part. There is no change to the form, fit inge. |
| Reason for Change: | | |
| | | |

Products Affected:

• MADL-011014-001000

Anticipated impact on Fit, Form, Function:

Form, Fit and Function unaffected.

Changes to product identification resulting from this PCN:

None