

MACOM
100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



19th December, 2025

Richardson RFPD, Inc.
2001 Butterfield Road, Suite 1800
Downers Grove, Illinois 60515

ATTN: Quality/Purchasing Manager

PCN-02027

Subject: Adding additional assembly and testing site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional assembly and testing site for the parts listed in the next pages.

In addition to our current sites, we plan to assemble and test these parts at our long-standing Contract Manufacturer, Year 2000, Ho Chi Minh City, Vietnam. Year 2000 is a valued, high-quality manufacturing partner for many MACOM products. The qualification report is available upon request.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely

Cindy Lien
Product Marketing Manager
cindy.lien@macom.com

PCN Number: PCN-02027		PCN Date: 19th Dec, 2025	
Title: Adding additional assembly and testing site.			
Proposed 1st Ship Date: After March 19th, 2026		Estimated Sample Availability: Based on the transfer progress of each part case by case	
Change Type:			
Assembly Site	X	Design	Electrical Specification
Test Site	X	Assembly Process	Mechanical Specification
Test Process		Assembly Materials	Packing/Shipping/Labeling
PCN Details			
Description of Change:			
MACOM has identified a second source to assemble and test the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change.			
Reason for Change:			
Increase the flexibility and continuity of supply.			
Products Affected:			
See next pages.			
Anticipated impact on Fit, Form, Function:			
Form, Fit and Function unaffected.			
Changes to product identification resulting from this PCN:			
None			

Appendix I
Affected part numbers.

No	Model	QBS vehicle
1	MA4P7435NM-1091T	-
2	MA4P7441F-1091T	MA4P7435NM-1091T
3	MA4P7446F-1091T	MA4P7435NM-1091T
4	MA4PH611NM	MA4P7435NM-1091T