

Product Change Notification: MFOL-28EKPY911

Date:

29-Oct-2024

Product Category:

RF/Microwave Modules & Assemblies, RF/Microwave Silicon and GaAs Diode Products

Notification Subject:

eSign# EOL0000335: End of Life (EOL) of MO9060-24, MO9081, MO9060, MO9061, MO9082-03, MO86561, MO86751A-M08, MO86562, MO9208, MO9208-01, MO9402, MO86728, MO86790-M22, MO86796, MO86860, MO86860-M07, MO87603C-1, MO9096, MO87859-2, and MO86656C-M03 catalog part numbers (CPN).

Affected CPNs:

MFOL-28EKPY911_Affected_CPN_10292024.pdf MFOL-28EKPY911 Affected CPN 10292024.csv

Notification Text:

PCN Status: End of Life (EOL) Notification

Microchip Parts Affected: Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The MO9060-24, MO9081, MO9060, MO9061, MO9082-03, MO86561, MO86751A-M08, MO86562, MO9208, MO9208-01, MO9402, MO86728, MO86790-M22, MO86796, MO86860, MO86860-M07, MO87603C-1, MO9096, MO87859-2, and MO86656C-M03 catalog part numbers (CPN) will be moving to End of Life (EOL) status effective today. These catalog part numbers will no longer be offered after November 01, 2025. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your Local Sales Representative.

Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates: Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

