

Radiall USA, Inc., 8950 South 52nd Street, Ste. 401, Tempe, Arizona 85284

TEL +1 480-682-9400

FAX +1 480-682-9401

10-10-2017

Subject: Discontinuation Notification – Partial QPL connector range

To whom it may concern;

Due to increasing Mil-QPL certification costing and declining sales, effective immediately, Radiall will be discontinuing a portion of our AEP QPL product line. The following 18 QPL parts will remain active and will remain MIL-QPL certified. We anticipate approval and requalification on the following 18 parts to be completed by the end of Q4, 2017.

Active AEP PN	Mil-QPL #	2017 Active Parts List
2002-1551-903	M39012/67-0004	Active
2002-1571-903	M39012/67B0009	Active
2002-1571-803	M39012/67B0010	Active
2001-1551-903	M39012/68-0004	Active
2001-1571-903	M39012/68B0009	Active
2001-1571-803	M39012/68B0010	Active
2005-1551-903	M39012/69-0004	Active
2003-1551-903	M39012/70-0004	Active
2004-1511-999	M39012/71-0001	Active
2019-1511-999	M39012/71-0002	Active
2009-1511-999	M39012/95-0001	Active
2009-1511-899	M39012/95-0002	Active
2009-1511-799	M39012/95-0003	Active
2009-6511-799	M39012/95-0006	Active
2010-1511-999	M39012/96-0001	Active
2010-1511-899	M39012/96-0002	Active
2010-1511-799	M39012/96-0003	Active
2010-6511-799	M39012/96-0006	Active

Below is a list of the MIL-QPL parts that will be discontinued. We are providing alternative QPL equivalent parts that meet the same performance criteria (form, fit and function) as the original AEP parts. These will not be MIL-QPL certified and will not have the Mil-QPL marking but have the exact same performances.

If necessary, we can provide Group A & B lot testing as required. This testing must be requested at the time of quotation and will have a separate lot testing charge.

Discontinued AEP PN	Mil-QPL #	Alternative QPL Equivalent PN
1001-1551-902	M39012/74-0003	1001-1551-102
1001-1551-903	M39012/74-0004	1001-1551-303
1001-1571-803	M39012/74B0010	1001-1571-103
1001-1571-902	M39012/74B0008	1001-1571-102
1001-1571-903	M39012/74B0009	1001-1571-203
1001-6551-902	M39012/74-0103	1001-6551-102
1001-6551-903	M39012/74-0104	1001-6551-303
1001-6571-803	M39012/74B0016	1001-6571-103
1001-6571-902	M39012/74B0014	1001-6571-102
1001-6571-903	M39012/74B0015	1001-6571-203
1002-1551-902	M39012/73-0003	1002-1551-202
1002-1551-903	M39012/73-0004	1002-1851-003
1002-1571-803	M39012/73B0010	1002-1571-503
1002-1571-902	M39012/73B0008	1002-1571-102
1002-1571-903	M39012/73B0009	1002-1571-603
1002-6551-902	M39012/73-0103	1002-6551-202
1002-6551-903	M39012/73-0104	1002-6851-003
1002-6571-803	M39012/73B0015	1002-6571-503
1002-6571-902	M39012/73B0013	1002-6571-102
1002-6571-903	M39012/73B0014	1002-6571-603
1003-1551-902	M39012/76-0003	1003-1551-102
1003-1551-903	M39012/76-0004	1003-1551-303
1003-1571-803	M39012/76B0010	1003-1571-203
1003-1571-902	M39012/76B0008	1003-1571-102
1003-1571-903	M39012/76B0009	1003-1571-303
1003-6551-902	M39012/76-0103	1003-6551-102
1003-6551-903	M39012/76-0104	1003-6551-303
1003-6571-803	M39012/76B0016	1003-6571-203
1003-6571-902	M39012/76B0014	1003-6571-102
1003-6571-903	M39012/76B0015	1003-6571-303
1004-1511-999	M39012/77-0001	1004-1511-011
1004-6511-999	M39012/77-0003	1004-6511-011
1005-1551-902	M39012/75-0003	1005-1551-202
1005-1551-903	M39012/75-0004	1005-1551-303

Radiall USA, Inc., 8350 South 52nd Street, Ste. 401, Tempe, Arizona 85284

TEL +1 480-682-9400

FAX +1 480-682-9401

Discontinued AEP PN	Mil-QPL #	Alternative QPL Equivalent PN
1005-6551-902	M39012/75-0103	1005-6551-202
1005-6551-903	M39012/75-0104	1005-6551-303
1019-1511-999	M39012/77-0002	1019-1511-017
1019-6511-999	M39012/77-0004	1019-6511-017
1105-1521-803	M39012/75B0010	1105-1521-703
1105-1521-902	M39012/75B0008	1105-1521-402
1105-1521-903	M39012/75B0009	1105-1821-003
1105-6521-803	M39012/75B0016	1105-6521-703
1105-6521-902	M39012/75B0014	1105-6521-402
1105-6521-903	M39012/75B0015	1105-6821-003
2001-1551-902	M39012/68-0003	2001-1551-102
2001-1571-902	M39012/68B0008	2001-1571-202
2001-6551-902	M39012/68-0103	2001-6551-102
2001-6551-903	M39012/68-0104	2001-6551-203
2001-6571-803	M39012/68B0015	2001-6571-403
2001-6571-902	M39012/68B0013	2001-6571-202
2001-6571-903	M39012/68B0014	2001-6571-603
2002-1551-902	M39012/67-0003	2002-1551-202
2002-1571-902	M39012/67B0008	2002-1571-302
2002-6551-902	M39012/67-0103	2002-6551-202
2002-6551-903	M39012/67-0104	2002-6551-603
2002-6571-803	M39012/67B0015	2002-6571-603
2002-6571-902	M39012/67B0013	2002-6571-302
2002-6571-903	M39012/67B0014	2002-6571-703
2003-1551-902	M39012/70-0003	2003-1551-302
2003-1571-803	M39012/70B0010	2003-1571-403
2003-1571-902	M39012/70B0008	2003-1571-502
2003-1571-903	M39012/70B0009	2003-1571-603
2003-6551-902	M39012/70-0103	2003-6551-302
2003-6551-903	M39012/70-0104	2003-6551-603
2003-6571-803	M39012/70B0015	2003-6571-403
2003-6571-902	M39012/70B0013	2003-6571-502
2003-6571-903	M39012/70B0014	2003-6571-603
2004-6511-999	M39012/71-0003	2004-6511-012
2005-1551-902	M39012/69-0003	2005-1551-202
2005-6551-902	M39012/69-0103	2005-6551-202

Radiall USA, Inc., 8950 South 52nd Street, Ste. 401, Tempe, Arizona 85284

TEL +1 480-682-9400

FAX +1 480-682-9401

Discontinued AEP PN	Mil-QPL #	Alternative QPL Equivalent PN
2005-6551-903	M39012/69-0104	2005-6551-403
2009-6511-899	M39012/95-0005	2009-6511-052
2009-6511-999	M39012/95-0004	2009-6511-053
2010-6511-899	M39012/96-0005	2010-6511-031
2010-6511-999	M39012/96-0004	2010-6511-032
2019-6511-999	M39012/71-0004	2019-6511-025
2105-1521-803	M39012/69B0010	2105-1921-603
2105-1521-902	M39012/69B0008	2105-1921-102
2105-1521-903	M39012/69B0009	2105-1921-503
2105-1921-803	M39012/69-0012	2105-1001-803
2105-6521-803	M39012/69B0015	2105-6921-603
2105-6521-902	M39012/69B0013	2105-6921-102
2105-6521-903	M39012/69B0014	2105-6921-503
2105-6921-903	M39012/69-0017	2105-1001-903
9101-9573-801	M39012/55-3128	9101-9573-301
9101-9573-802	M39012/55-3125	9101-9573-302
9101-9573-803	M39012/55-3126	9101-9873-003
9101-9573-806	M39012/55-3129	9101-9573-106
9101-9573-830	M39012/55-3127	9101-9573-130
9101-9573-901	M39012/55-3028	9101-9573-401
9101-9573-902	M39012/55-3025	9101-9573-402
9101-9573-903	M39012/55-3026	9101-9973-003
9101-9573-906	M39012/55-3029	9101-9573-206
9101-9573-930	M39012/55-3027	9101-9573-230
9201-9553-801	M39012/55-3109	9201-9553-301
9201-9553-802	M39012/55-3106	9201-9553-302
9201-9553-803	M39012/55-3107	9201-9553-403
9201-9553-806	M39012/55-3110	9201-9553-106
9201-9553-830	M39012/55-3108	9201-9553-130
9201-9553-901	M39012/55-3009	9201-9553-401
9201-9553-902	M39012/55-3006	9201-9553-402
9201-9553-903	M39012/55-3007	9201-9553-503
9201-9553-906	M39012/55-3010	9201-9553-206
9201-9553-930	M39012/55-3008	9201-9553-230
9230-9553-901	M39012/59-3009	9230-9553-101
9230-9553-902	M39012/59-3006	9230-9553-602

Radiall USA, Inc., 8950 South 52nd Street, Ste. 401, Tempe, Arizona 85284

TEL +1 480-682-9400

FAX +1 480-682-9401

Discontinued AEP PN	Mil-QPL #	Alternative QPL Equivalent PN
9230-9553-903	M39012/59-3007	9230-9553-103
9230-9553-906	M39012/59-3010	9230-9553-106
9230-9553-930	M39012/59-3008	9230-9553-130
9301-1003-909	M39012/92B3101	9301-1803-009
9301-1063-909	M39012/92B3001	9301-1863-009
9404-9113-999	M39012/60-3001	9404-9113-009
9408-9113-999	M39012/60-3002	9408-9113-007
9432-9113-999	M39012/61-3001	9432-9113-001
9465-9113-999	M39012/61-3002	9465-9113-001
9501-9593-809	M39012/79B3104	9501-9593-409
9501-9593-810	M39012/79B3103	9501-9593-110
9501-9593-909	M39012/79B3004	9501-9593-509
9501-9593-910	M39012/79B3003	9501-9593-210
9530-9593-909	M39012/83B3004	9530-9593-209
9530-9593-910	M39012/83B3003	9530-9593-210

Please do not hesitate to contact your local sales representative or authorized distributors if you have any requests for the alternative parts.

Sincerely,



Ross Martinez
North American RF&I Marketing Manager