

October 21, 2021

## Product Change Notification

Customer: All  
P/N: See table below

TTM RF&S Order#: All  
Qty Affected: All


### Notice of Change(s):

TTM RF&S would like to inform of a part dimension change for the 0603 sized components listed in the table below.


|                 |
|-----------------|
| X0060L5050AHF   |
| X0060L7575AHF   |
| BD3150L50100AHF |
| PD4859L5050S2HF |
| PD2635L5050S2HF |
| BD2326L50200AHF |
| BD2326L50150AHF |

The drawings below detail the change (see highlighted in yellow). There is **no change** in the footprint and **no change** in the functionality and performance of these parts.

### Previous Mechanical Outline:



## New Mechanical Outline:



## Justification:

This change has been implemented as part of a continuous process improvement.

## Timeline:

Parts with the updated dimension will begin shipping once existing stock is exhausted. Our estimated shipment dates are provided per the dates specified in the table below.

|                 |               |
|-----------------|---------------|
| BD2326L50200AHF | November,2021 |
| X0060L5050AHF   | February,2022 |
| X0060L7575AHF   | February,2022 |
| BD3150L50100AHF | March,2022    |
| PD4859L5050S2HF | March,2022    |
| PD2635L5050S2HF | March,2022    |

To help determine the impact of this change on customer system, samples of parts with the new size can be made available as needed.

If you have any questions or need further information, please call me at 1-315-233-5510 or send e-mail to [Sarvesh.nair@ttm.com](mailto:Sarvesh.nair@ttm.com)

Sincerely,  
Sarvesh Nair  
Product Line Manager  
TTM Technologies Company  
<http://www.ttm.com>