

Customer Notification of

☒ **PRODUCT- /** ☐ **PROCESS CHANGE**

(According to JEDEC Standard J-STD-046 July 2016)

Vincotech – PCN – No 2025-038

SUBJECT OF CHANGE:	Wafer size change from 4" to 6" of rectifier
PRODUCTS AFFECTED:	See products below
REASON OF CHANGE:	Improved component availability

CLASSIFICATION OF CHANGE:	MINOR (only for information, no customer acknowledgement required)
----------------------------------	--

DESCRIPTION OF CHANGE:

SUBJECT	CURRENT	NEW
wafer size	4" wafer	6" wafer

ANTICIPATED IMPACT ON:

Form:	No
Fit:	No
Function:	No
Others:	No

TIME SCHEDULE:

Final qualification report:	Accomplished according to standard qualification
First samples available:	According to the standard delivery time
Earliest implementation date:	2026-febr.-16

PRODUCT IDENTIFICATION:

Part#	Current Revision	New Revision
V23990-P549-A-PM	n	n
V23990-P540-A-PM	n	n
V23990-P544-A20-PM	n	n
V23990-P545-A20-PM	n	n
V23990-P546-A20-PM	n	n
V23990-P580-C-PM	n	n
V23990-P585-A20-PM	n	n
V23990-P586-A20-PM	n	n
V23990-P587-A20-PM	n	n
V23990-P587-C20-PM	n	n
V23990-P632-A-PM	n	n
V23990-P633-A-PM	n	n





Part#	Current Revision	New Revision
V23990-P634-A-PM	n	n
V23990-P635-A-PM	n	n
V23990-P630-A-PM	n	n
V23990-P545-A21-PM	n	n
V23990-P546-A21-PM	n	n
V23990-K204-A-PM	n	n
V23990-P213-A04-PM	n	n
V23990-P211-A04-PM	n	n
V23990-P211-D04-PM	n	n
V23990-P840-A48-PM	n	n
V23990-P840-A49-PM	n	n
V23990-P849-A48-PM	n	n
V23990-P849-A49-PM	n	n
V23990-P849-C48-PM	n	n
V23990-P849-C49-PM	n	n
V23990-P840-C48-PM	n	n
V23990-P840-C49-PM	n	n
V23990-P589-A41-PM	n	n
V23990-P580-A41-PM	n	n
V23990-P840-A58-PM	n	n
V23990-P848-A48-PM	n	n
V23990-P848-A58-PM	n	n
V23990-P848-C58-PM	n	n
V23990-P849-A58-PM	n	n
V23990-P849-C58-PM	n	n
V23990-P588-A41-PM	n	n
V23990-P840-A59-PM	n	n
V23990-P848-A49-PM	n	n
V23990-P848-C49-PM	n	n
V23990-P849-A59-PM	n	n
V23990-K209-A-/1A/-PM	n	n
V23990-K209-A-/0B/-PM	n	n
V23990-K209-A-/1B/-PM	n	n
V23990-K202-A-/1B/-PM	n	n
V23990-K203-A-/1B/-PM	n	n
V23990-K220-A-/1B/-PM	n	n
V23990-K229-A-/1B/-PM	n	n
V23990-P546-C39-PM	n	n
V23990-K220-A40-/0A/-PM	n	n
V23990-K229-A40-/0A/-PM	n	n
V23990-K220-A-/0A/-PM	n	n
V23990-P541-A28-PM	n	n
V23990-P543-A28-PM	n	n





Part#	Current Revision	New Revision
V23990-P544-A28-PM	n	n
V23990-P545-A28-PM	n	n
V23990-P545-C39-PM	n	n
V23990-P546-A28-PM	n	n
V23990-K209-A40-/0A/-PM	n	n
V23990-K200-A40-/0A/-PM	n	n
V23990-K200-A-/1A/-PM	n	n
V23990-K220-A-/1A/-PM	n	n
V23990-K229-A-/1A/-PM	n	n
V23990-K229-A-/0A/-PM	n	n
V23990-P588-C88-PM	n	n
V23990-K220-A40-/1A/-PM	n	n
V23990-P580-C41-PM	n	n
V23990-P588-C41-PM	n	n
V23990-P589-C41-PM	n	n
V23990-P543-B28-PM	n	n
V23990-P544-B28-PM	n	n
V23990-P545-B28-PM	n	n
V23990-P546-B28-PM	n	n
V23990-P449-C33-PM	n	n
V23990-P586-A20Y-PM	n	n
V23990-P585-A20Y-PM	n	n
V23990-K223-A-/0A/-PM	n	n
80-M012PNB008SB-K619C31-/0B/	n	n
V23990-K200-A-/0B/-PM	n	n
80-M006PNB010SA01-K615D-/0B/	n	n
V23990-K229-A-/0B/-PM	n	n
V23990-K220-A-/0B/-PM	n	n
V23990-K222-A-/0B/-PM	n	n
V23990-K203-B-/0B/-PM	n	n
80-M006PNB010SA-K615C-/0B/	n	n
80-M012PNB008SC-K619C41-/0B/	n	n
V23990-K223-A-/0B/-PM	n	n
V23990-K200-A40-/0B/-PM	n	n
V23990-K229-A40-/0B/-PM	n	n
V23990-K220-A40-/0B/-PM	n	n
V23990-K201-A-/0A/-PM	n	n
V23990-P840-A79-PM	n	n
V23990-P586-A208-PM	n	n
V23990-P589-A418-PM	n	n
V23990-P541-B138-PM	n	n
V23990-P543-B138-PM	n	n
V23990-P543-D138-PM	n	n





Part#	Current Revision	New Revision
V23990-K229-A40-/1A/-PM	n	n
V23990-K203-A-/0B/-PM	n	n
V23990-P541-D129-PM	n	n
V23990-P543-D129-PM	n	n
V23990-P544-B129-PM	n	n
V23990-P543-C29-PM	n	n
V23990-P544-A29-PM	n	n
V23990-K200-A40-/1B/-PM	n	n
V23990-P545-B129-PM	n	n
V23990-P580-A418-PM	n	n
10-F006PPA010SB-M683B	n	n
V23990-P630-A40-PM	n	n
V23990-P630-A44-PM	n	n
V23990-P639-A40-PM	n	n
V23990-P580-C41-/3/-PM	n	n
V23990-P849-A59Y-PM	n	n
V23990-P588-A418-PM	n	n
V23990-P585-A208-PM	n	n
V23990-P629-L49-PM	n	n
10-F006PPA010SB-M683B-/3/	n	n
V23990-K203-A-/1A/-PM	n	n
V23990-K209-A40-PM	n	n
10-F0166RA050SC-M920G29-/3/	n	n
V23990-K222-A-/1A/-PM	n	n
V23990-P543-A28-/3/-PM	n	n
V23990-P545-A28-/3/-PM	n	n
10-R106PPA020SB01-M934A	n	n
V23990-P629-L43-PM	n	n
V23990-P629-L43-PM	n	n
V23990-K209-A40-/0B/-PM	n	n
10-0B166BA028SC-M989G09	n	n
V23990-P543-A29-PM	n	n
V23990-P543-B129-PM	n	n
V23990-P541-A29-PM	n	n
V23990-P543-B28-/3/-PM	n	n
V23990-P544-B28-/3/-PM	n	n
V23990-P545-B28-/3/-PM	n	n
V23990-P546-B28-/3/-PM	n	n
V23990-P840-A48-/3/-PM	n	n
V23990-P849-A48-/3/-PM	n	n
V23990-K200-A-/1B/-PM	n	n
10-PZ164RB140RW-M460J68Y	n	n
V23990-P580-A47-PM	n	n





Part#	Current Revision	New Revision
V23990-K209-A40-/1B/-PM	n	n
V23990-P629-L48Y-PM	n	n
V23990-K222-B10-/0B/-PM	n	n
V23990-P849-C48-/3/-PM	n	n
V23990-P840-C48-/3/-PM	n	n
V23990-P629-L57-PM	n	n
V23990-P543-D28-/3/-PM	n	n
V23990-P546-D28-/3/-PM	n	n
V23990-P543-D28-PM	n	n
V23990-P634-A-/3/-PM	n	n
10-LZ07BIA040SM06-M036E48	n	n
V23990-P546-A28-/3/-PM	n	n
V23990-P630-A40-/3/-PM	n	n
10-LY12PMA035SC-L188A48	n	n
80-M012PNB008SC-K619C41-/1A/	n	n
V23990-P543-C28-/3/-PM	n	n
V23990-P546-C28-/3/-PM	n	n
V23990-K209-A40-/1A/-PM	n	n
V23990-P629-L49Y-PM	n	n
V23990-P629-L48-PM	n	n
V23990-P588-C41-/3/-PM	n	n
V23990-P849-A59-/3/-PM	n	n
V23990-P580-C418-PM	n	n
10-F006PMA030SC-L413A09	n	n
10-F012PMA015SC-L419A09	n	n
10-F006PMA030SC-L413A09-/3/	n	n
V23990-K203-B10-/0B/-PM	n	n
V23990-K203-B10-/10/-PM	n	n
V23990-K209-A40-/10/-PM	n	n
V23990-K222-B10-/10/-PM	n	n
V23990-K427-A40-/10/-PM	n	n
V23990-K200-A40-/10/-PM	n	n
V23990-P849-A49Y-PM	n	n
V23990-P629-L43-/3/-PM	n	n
V23990-P629-L43-/3/-PM	n	n
10-PD06PPA015SB02-M684B17Y	n	n
10-FY07BIA050SM-M523E38	n	n
10-PY07BIA050SM-M523E38Y	n	n
V23990-P848-C49-/3/-PM	n	n
10-ZB186RA035RJ-L609H08	n	n
V23990-P629-L43Y-PM	n	n
V23990-P629-L43Y-PM	n	n
10-PY07BIA050SM-M523E38Y-/3/	n	n





Part#	Current Revision	New Revision
V23990-P541-D28-PM	n	n
V23990-P629-L43Y-/3/-PM	n	n
V23990-P629-L43Y-/3/-PM	n	n
10-FY0726A040S503-L434E58	n	n
10-PD06PPA015SB02-M684B17Y-/3/	n	n
V23990-P580-C418-/3/-PM	n	n
V23990-P589-C418-/3/-PM	n	n
V23990-P630-A44-/3/-PM	n	n
V23990-P580-A418-/3/-PM	n	n
V23990-P545-A39-PM	n	n
10-FZ071SA075S501-L525L58	n	n
10-FZ071SA075S5-L694L58	n	n
10-LY12PMA035SC-L188A48-/3/	n	n
10-P0166RA050SC-M920G29Y	n	n
20-FB06IMA015RC-L234C08Y-/3/	n	n
10-FY07ZAB075SM-L515B08	n	n
10-P006PPA010SB-M683BY	n	n
V23990-P544-C29-PM	n	n
V23990-P545-C29-PM	n	n
V23990-P546-C29-PM	n	n
V23990-P629-L48Y-/3/-PM	n	n
V23990-P632-A-/3/-PM	n	n
80-M312PMA100M7-K420A70	n	n
80-M312PMA075M7-K429A70-/1A/	n	n
V23990-P589-C418-PM	n	n
V23990-P840-A58Y-/3/-PM	n	n
V23990-K204-A-/0A/-PM	n	n
V23990-P629-L48-/3/-PM	n	n
80-M312PMA075M7-K429A70-/0A/	n	n
10-EZ12PMA010SC-L927A08T	n	n
10-EY12PMA035SC-L188A48T	n	n
10-EY12PMA025SC-L187A48T	n	n
V23990-P546-C28-PM	n	n
10-FZ12PMA005M7-P848A28	n	n
10-FZ12PMA010M7-P849A28	n	n
10-FZ12PMA015M7-P840A28	n	n
80-M212PMA025M7-K229A70-/5A/	n	n
80-M212PMA035M7-K220A70-/5A/	n	n
10-FY12PMA015M7-P587A78	n	n
10-FY12PMA025M7-P588A78	n	n
80-M112PMA010M7-K209A70-/0A/	n	n
80-M112PMA015M7-K200A70-/0A/	n	n
80-M012PNA010M7-K619C71-/0B/	n	n





Part#	Current Revision	New Revision
10-F112PMA015M7-P587A79	n	n
10-F112PMA025M7-P588A79	n	n
10-F012PMA005M7-P848A29	n	n
10-F012PMA010M7-P849A29	n	n
10-F012PMA015M7-P840A29	n	n
80-M312PMA050M7-K428A70	n	n
80-M3126SA050M7-K858E70-/5A/	n	n
80-M212PMA035M7-K220A70-/0A/	n	n
80-M212PMA025M7-K229A70-/0A/	n	n
10-EZ07B1A040RG-M045L78T	n	n
V23990-P589-A418Y-/3/-PM	n	n
V23990-P849-A48Y-/3/-PM	n	n
10-R112PMA015M7-P639A75	n	n
10-R112PMA025M7-P630A70	n	n
10-EZ073BB040RG-M086L88T	n	n
10-EY12PMA035SC-L188A48T-/3/	n	n
80-M312PMA050M7-K428A70-/0A/	n	n
V23990-K229-A40-PM	n	n
80-M012PMA010M7-K619C71-/5B/	n	n
80-M312PMA050M7-K428A70-/5B/	n	n
80-M312PMA075M7-K429A70-/5B/	n	n
80-M312PMA100M7-K420A70-/5B/	n	n
80-M112PMA010M7-K209A70-/5B/	n	n
80-M112PMA015M7-K200A70-/5B/	n	n
80-M212PMA025M7-K229A70-/5B/	n	n
80-M212PMA035M7-K220A70-/5B/	n	n
10-EZ12PMA010M7-L927A78T	n	n
10-EZ12PMA015M7-L928A78T	n	n
10-EY12PMA015M7-L186A78T	n	n
10-EY12PMA025M7-L187A78T	n	n
10-EY12PMA035M7-L188A78T	n	n
V23990-K200-A40-/5A/-PM	n	n
V23990-K209-A40-/5A/-PM	n	n
V23990-K220-A40-/5A/-PM	n	n
V23990-K229-A40-/5A/-PM	n	n
V23990-K200-A10-/5B/-PM	n	n
10-F106PSA075SA-LG65A09-/3/	n	n
80-M112PMA015M7-K200A70-/5A/	n	n
80-M312PMA075M7-K429A70-/5A/	n	n
80-M312PMA100M7-K420A70-/5A/	n	n
V23990-K220-A40-PM	n	n
V23990-K204-A-/5A/-PM	n	n
V23990-K223-A-/5A/-PM	n	n





Part#	Current Revision	New Revision
V23990-K203-A-PM	n	n
80-M112PMA010M7-K209A70-/0B/	n	n
80-M112PMA015M7-K200A70-/0B/	n	n
80-M212PMA035M7-K220A70-/0B/	n	n
10-FY0726A040S503-L434E582	n	n
V23990-P629-L57Y-PM	n	n
80-M112PMA015M7-K200A70-/1A/	n	n
80-M112PMA010M7-K209A70-/1A/	n	n
10-EZ06PMA030SA-L926A38T	n	n
10-EY06PMA050SA-L184A38T	n	n
10-EZ06PMA010SA-L923A38T	n	n
10-EZ06PMA020SA-L925A38T	n	n
80-M212PMA035M7-K220A70-/1A/	n	n
10-F112PMA025M7-P588A79-/3/	n	n
V23990-P543-A28Y-/3/-PM	n	n
V23990-P545-A28Y-/3/-PM	n	n
V23990-P546-A28Y-/3/-PM	n	n
10-R112PMA015M7-P639A75-/3/	n	n
V23990-K229-A10-/5B/-PM	n	n
10-FZ12PMA015M7-P840A28-/3/	n	n
10-FZ12PMA010M7-P849A28-/3/	n	n
80-M3166BA110RJ01-K469G11-/5A/	n	n
80-M0126BA050SC-K629G-/5A/	n	n
10-EY06PMA050SA-L184A38T-/3/	n	n
80-M012PNA010M7-K619C71-/5A/	n	n
80-M312PMA050M7-K428A70-/5A/	n	n
10-F012PNA015M7-P840C29	n	n
80-M112PMA010M7-K209A70-/5A/	n	n
10-EZ12PNA010M7-L927C78T	n	n
10-EZ12PNA015M7-L928C78T	n	n
10-FZ12B2A080MR04-P629L82	n	n
10-PG06PPA030SJ-LJ02B08T	n	n
10-E112PNA010M7-L927C78Z-/3/	n	n
10-E112PNA015M7-L928C78Z-/3/	n	n
10-E206PMA050SA-L184A38Z	n	n
10-FZ12PMA010M701-P849A288	n	n
10-FZ12PMA005M701-P848A288	n	n
10-FZ12PMA015M701-P840A288	n	n
10-PG06PPA050SJ-LJ04B08T	n	n
10-EZ12PMA025M7-L929A78T	n	n
10-EY12PMA050M7-L189A78T	n	n
10-E212PMA035M7-L188A78Z-/3/	n	n
10-E212PMA025M7-L187A78Z-/3/	n	n





Part#	Current Revision	New Revision
10-E212PMA025M7-L187A78Z	n	n
10-PF12B2A050SH03-LJ89L03T	n	n
10-FZ12PNA015M7-P840C28-/3/	n	n
10-FZ12PNA010M7-P849C28-/3/	n	n
10-E212PMA035M7-L188A78Z	n	n
V23990-P586-C208-/3/-PM	n	n
10-PZ12PMA015M7-P840A28Y-/3/	n	n
10-E112PMA010M7-L927A78Z	n	n
10-E112PMA015M7-L928A78Z	n	n
10-P112PMA025M7-P588A79Y-/3/	n	n
V23990-P585-A20Y-/3/-PM	n	n
V23990-P586-A20Y-/3/-PM	n	n
80-M2166BA075AS-K369G71-/5A/	n	n
80-M112PMA025M7-K200A80-/5B/	n	n
10-F112PSA035M7-LG69A79-/3/	n	n
10-R112PMA025M7-P630A70-/3/	n	n
10-F012PMA005M7-P848A29-/3/	n	n
10-F012PMA010M7-P849A29-/3/	n	n
10-F012PMA015M7-P840A29-/3/	n	n
80-M212PMA025M7-K229A70-/0B/	n	n
10-EY12PNA025M7-L187C78T	n	n
10-EY12PNA035M7-L188C78T	n	n
80-M312PMA150M7-K420A80	n	n
10-FY123BA080SH03-LN28L47	n	n
10-FY12S2A075SH-L860L48	n	n
V23990-P545-D28-/3/-PM	n	n
10-F006PPA010SB03-M683B50	n	n
80-M212PMB015SC-K228A42-/5B/	n	n
80-M212PMB025SC-K229A42-/5B/	n	n
80-M212PMB035SC-K220A42-/5B/	n	n
80-M312PMA100M702-K420A74-/5B/	n	n
10-E212PMA050M7-L189A78Z	n	n
10-E112PNA015M7-L928C78Z	n	n
80-M112PMA015M7-K200A70-/4A/	n	n
10-F012PNA005M7-P848C29	n	n
80-M212PMA035M731-K220A72-/5B/	n	n
80-M312PMA150M7-K420A80-/5A/	n	n
10-PC09RHA225P7-LG83C96Y	n	n
80-M2166BA075RJ-K769G40-/5B/	n	n
10-E112PMA010M7-L927A78Z-/3/	n	n
10-E112PMA015M7-L928A78Z-/3/	n	n
V23990-K209-A40-/5B/-PM	n	n
10-F012PMB015M7-L419A79-/3/	n	n





Part#	Current Revision	New Revision
10-PZ166RA050SC-M920G28Y	n	n
V23990-K201-A-/5B/-PM	n	n
80-M212WPA015M7-K757F70-/5A/	n	n
80-M312WPA075M7-K880F70-/5A/	n	n
80-M312PMA100M7-K420A70-/0B/	n	n
80-M312PMA050M7-K428A70-/0B/	n	n
80-M312PMA075M7-K429A70-/0B/	n	n
V23990-K204-A-/5B/-PM	n	n
V23990-K200-A40-/5B/-PM	n	n
10-TY06PMA030SA-P585A206	n	n
30-PT09HBA100S707-LJ39L80Y	n	n
80-M212WPA050M7-K750F70-/5A/	n	n
80-M312PMA050M7-K428A70-/1A/	n	n
80-M212PMA025M7-K229A70-/1A/	n	n
10-PY166RA170JR-LR59H08Y-/3/	n	n
10-PZ12PMA015M7-P840A28Y	n	n
10-PY12PMA025M7-P588A78Y	n	n
10-PG06PPA020SJ-LJ01B08T	n	n
V23990-K201-A-/5A/-PM	n	n
10-0B166RA028RJ-M989H09-/3/	n	n
10-EZ12PMA025M7-L929A78T-/3/	n	n
10-FY07BIA030SM07-LT14E08	n	n
10-F006PPA010M701-LT23B79-/3/	n	n
10-E112PMA025M7-L929A78Z-/3/	n	n
10-EZ17SWA150M701-LU09F78T	n	n
10-FZ12PNA015M7-P840C28	n	n
V23990-P544-A27Y-/3/-PM	n	n
20-FB06IMA015RC02-L234C03Y-/3/	n	n
10-E112PMA025M7-L929A78Z	n	n
10-PG06PPA030SJ04-LJ02B03T	n	n
80-M112PMA015M7-K200A70-/1B/	n	n
10-E107PSA015M7-LU74A08Z-/3/	n	n
10-E112PSA010M7-LU77A08Z-/3/	n	n
10-E112PNA010M7-L927C78Z	n	n
10-EY12PMA050M7-L189A78T-/3/	n	n
80-M212PNB015M7-K778C70-/5A/	n	n
80-M312PNB035M7-K937C70-/5A/	n	n
80-M312PNB050M7-K938C70-/5A/	n	n
10-EY12PMA025M7-L187A78T-/3/	n	n
10-EY12PMA025SC-L187A48T-/3/	n	n
B0-SL10S3A100S710-LR69L03Z-/7/	n	n
10-PG06PPA050SJ-LJ04B08T-/3/	n	n
V23990-K220-A40-/5B/-PM	n	n





Part#	Current Revision	New Revision
10-E212PMA025SC-L187A48Z	n	n
V23990-K200-A10-/5A/-PM	n	n
10-F012PNA015M7-P840C29-/3/	n	n
10-PG123BA080SH11-LN68L33T	n	n
10-P012PMA010M7-P849A29Y-/3/	n	n
10-PG123BA080SH21-LN68L18T	n	n
10-PY166RA170JR-LR59H08Y	n	n
80-M2126PC075M7-K780F70-/5A/	n	n
B0-SL10B2A200S705-PA58L96Z-/7/	n	n
10-FE12APA015SH01-PB18E08Z	n	n
V23990-K222-A-/5A/-PM	n	n
80-M106PRA020SA30-K954D30-/5B/	n	n
10-FZ07B2A030SM08-M575L408	n	n
10-FZ073BA030SM07-M575L308	n	n
10-FE06PPA030SJ04-LJ02B03Z	n	n
10-R112PNA025M7-P630C70	n	n
10-FE06PPA020SJ01-LK23B58Z-/3/	n	n
B0-SP10S3A100S710-LR69L03T-/7/	n	n
10-F006PPA010SB03-M683B50-/3/	n	n
10-FE06PPA030SJ03-LK24B18Z-/3/	n	n
80-M006PNB010SA-K615C-/1A/	n	n
B0-SP10B2A200S705-PA58L96T-/7/	n	n
V23990-K203-A-/5B/-PM	n	n
10-F012PNA005M7-P848C29-/3/	n	n
10-FY123BA080SH03-LN28L47-/3/	n	n
V23990-K202-A-/5B/-PM	n	n
10-PG12APA015SH01-PB18E08T	n	n
10-FY07ZAA055F7-L513B78-/3/	n	n
80-M112PMA025M7-K200A80-/5A/	n	n
10-R112PMB025SC-LV50A45-/3/	n	n
10-PY12S2A036MR02-L869L98Y	n	n
10-F112PMA015M7-P587A79-/3/	n	n
10-FY12B2A032ME-L387L28	n	n
10-FZ071SA075RG01-L525L68	n	n
10-FZ071SA075RG02-L694L68	n	n
B0-SL12PPA040SH-PC88L41Z-/7/	n	n
10-FZ07B2A030RG03-M575L488	n	n
10-FZ073BA030RG01-M575L388	n	n
80-M3126SB50M7-K969A-/5A/	n	n
V23990-K280-A71-/4A/-PM	n	n
30-FT20SWA800M7-PD49F78	n	n
10-P106PPA050SJ-PD54B09Y	n	n
10-F006PPA015SB04-M684B09	n	n





Part#	Current Revision	New Revision
V23990-P629-L57-/3/-PM	n	n
10-F006PPA020SB03-M685B09	n	n
10-F006PPA020SB03-M685B09-/3/	n	n
10-E106PMA030SA-L926A38Z	n	n
10-PG07B2A075SM01-PA15L48T	n	n
10-P006PPA020SB03-M685B09Y	n	n
10-P006PPA020SB03-M685B09Y-/3/	n	n
10-PY166RA110RW-LR58H08Y-/7/	n	n
10-PJ12B2A050SH06-LJ89L48T	n	n
10-EY12PNA032ME02-L188C03T	n	n
10-EY12PNA040MR02-L188C13T	n	n
10-FY07BIA030SM07-LT14E082	n	n
10-P106PPA050SJ-PD54B09Y-/3/	n	n
10-P106PPA050SJ-PD54B09Y-/7/	n	n
10-PC073AA030SM-PF04H06Y	n	n
10-PY166RA170JR-LR59H08Y-/7/	n	n
10-FZ073BA030RG02-M575L378	n	n
B0-SP12PPA040SH-PC88L41T-/7/	n	n
10-FZ07B2A030RG04-M575L478	n	n
80-M212PMB035M7-K220A71-/5A/	n	n
V23990-P840-C49-/3/-PM	n	n
10-F006PPA010M701-LT23B79	n	n
10-FZ073BA030SM07-M575L308-/3/	n	n
10-FU073AA030SM-PF04H06	n	n
10-PC07PQA040S5-P546B56Y-/7/	n	n
10-PY166RA050RW-LR56H08Y-/7/	n	n
80-M012PNA010M7-K619C71-/50/	n	n
10-FY12PMA025SH01-P589A81-/3/	n	n
10-FZ06BIA090F7-P896E78-/3/	n	n
10-FZ06BIA145F7-P892E78-/3/	n	n
80-M212WPA050M701-K750F71-/5A/	n	n
30-PT12B6A032ME01-PF77L08Y	n	n
10-E212PNA035M7-L188C78Z	n	n
10-E212PMA050M7-L189A78Z-/3/	n	n
10-EY12PNA032ME02-L188C03T-/3/	n	n
10-R112PNA015M7-P639C75	n	n
80-M112PMA010M7-K209A70-/4A/	n	n
10-EZ12B1A080N305-LT09L42T	n	n
10-PZ07B2A030SM11-P622L58Y-/3/	n	n
B0-SP12ORA080RO01-LM90I48T-/7/	n	n
B0-SP12ORA080RO-LM90J48T-/7/	n	n
10-FY073AA030RG04-LK12L03-/3/	n	n
80-M212PMA035M731-K220A72-/5A/	n	n



Part#	Current Revision	New Revision
80-M112PMA015M701-K200A71-/5A/	n	n
80-M112PMA015M702-K200A72-/5A/	n	n
V23990-K280-A72-/4A/-PM	n	n
10-EZ123BA036MR-PH39L08T	n	n
10-FE06PPA020SJ-LJ01B08Z-/3/	n	n
10-P006PPA010SB-M683BY-/7/	n	n
10-FY12PMA025M7-P588A78-/7/	n	n
10-FZ073BA030SM01-M575L318-/7/	n	n
10-F006RIA075F2-P905D49-/3/	n	n
10-E112PMA015M701-L928A73Z-/3/	n	n
80-M112PMA010M7-K209A70-/1B/	n	n
10-E212PNA035M7-L188C78Z-/3/	n	n
10-PG06PPA050SJ-LJ04B08T-/7/	n	n
10-PG06PPA030SJ-LJ02B08T-/7/	n	n
10-PG06PPA020SJ-LJ01B08T-/7/	n	n
10-FY12APA036MR-PB18E98Z	n	n
10-EZ12B2A036MR-PH39L03T	n	n
80-M312PMA150M7-K420A80-/5B/	n	n
10-FE12APA015SH01-PB18E08Z-/7/	n	n
10-FY12APA036MR-PB18E98Z-/7/	n	n
30-FT12B2A200H701-PK49L08	n	n
30-PT12B2A200H701-PK49L08Y	n	n
30-FT12B2A200H702-PK49L03	n	n
30-PT12B2A200H702-PK49L03Y	n	n
10-FU07PMA030I7-P546B66	n	n
10-FZ12PNA010M7-P849C28	n	n
10-FZ12PNA005M7-P848C28	n	n
10-E112PNA015M7-L928C78Z-/7/	n	n
10-PG07B2A075F202-PA15L83T	n	n
10-RW12PMA015M7-P639A76-/3/	n	n
10-RW12PMA025M7-P630A76-/3/	n	n
V23990-P634-A36-/3/-PM	n	n
10-PZ07B2A030SM11-P622L58Y-/7/	n	n
30-PT12B2A200H703-PK89L08T	n	n
10-E106PMA020SA-L925A38Z	n	n
10-EZ123BA036MR-PH39L08T-/3/	n	n
10-PZ12B2A075ME-P621L18Y	n	n
80-M212PMA025M7-K229A70-/1B/	n	n
10-PG123BA080SH21-LN68L18T-/3/	n	n
10-FY12B2A032ME-L387L28-/3/	n	n
10-E112PMA015M701-L928A73Z	n	n
10-FZ07BVA030S501-LD45E18	n	n
10-FZ12PMA015M7-P840A28-/7/	n	n





Part#	Current Revision	New Revision
10-E212PMA025M7-L187A78Z-/7/	n	n
10-EY12PNA035M7-L188C78T-/7/	n	n
10-EY12PMA050M7-L189A78T-/7/	n	n
10-EZ06PMA020SA-L925A38T-/3/	n	n
V23990-K223-A-/5B/-PM	n	n
10-EZ06PMA010SA-L923A38T-/3/	n	n
10-EZ06PMA030SA-L926A38T-/3/	n	n
10-F4166RB070RW-PM70H04	n	n
10-E107PMA020I7-L925A28Z	n	n
10-E107PMA030I7-L926A28Z	n	n
10-F112PMA040SH02-P580A82-/7/	n	n
10-FZ07B1A030SM01-M575L18-/7/	n	n
10-FZ07B2A030SM01-M575L68-/7/	n	n
10-E106PMA030SA-L926A38Z-/7/	n	n
10-PG06PPA030SJ04-LJ02B03T-/7/	n	n
30-FT12B2A200H705-PK49L06	n	n
30-FT12B2A200H706-PK49L01	n	n
10-EZ12B2A036MR-PH39L03T-/7/	n	n
80-M112PMA015M701-K200A71-/5B/	n	n
10-P112PMA040SH02-P580A82Y-/7/	n	n
80-M212PMB035M7-K220A71-/5B/	n	n
10-EZ123BA036MR-PH39L08T-/7/	n	n
10-FY07PPA050I702-LK25B28Z-/7/	n	n
10-E206PMA050SA-L184A38Z-/7/	n	n
10-PC07PMA020I7-P545B66Y-/7/	n	n
30-PT20DWA400M701-PH40F78T	n	n
10-F012PMB015M702-L419A75-/7/	n	n
V23990-P629-L57Y-/7/-PM	n	n
10-F012PMB015M702-L419A75-/3/	n	n
10-F0166RA050SC-M920G29	n	n
10-FY073AA030RG04-LK12L03	n	n
30-PT12B2A200H704-PK89L03T	n	n
80-M212PMB050M7-K740A71-/5B/	n	n
10-FY12PMA025SH01-P589A81	n	n
30-PT12B2A200H733-PK89L10T	n	n
30-PT12HBA200H702-PC39L22T	n	n
30-PQ12B2A200H703-PK89L07T	n	n
30-PQ12B2A200H704-PK89L02T	n	n
10-E112PMA015M7-L928A78Z-/7/	n	n
80-M112PMA010M7-K209A70-/50/	n	n
80-M312PMA100M7-K420A70-/50/	n	n
80-M112PMA025M7-K200A80-/50/	n	n
80-M212PMA035M7-K220A70-/50/	n	n



Vincotech

Part#	Current Revision	New Revision
10-FY12B2A032ME-L387L28-/7/	n	n
10-0B166BA028SC-M989G09-/7/	n	n
80-M212PMB050M7-K740A71-/5A/	n	n
80-M212PMB050M7-K740A71-/0B/	n	n
10-PY166RA050RW-LR56H08Y	n	n

Important information for your attention:

Minor change:

- For information purpose only (no customer acknowledgement required)

Major change:

- Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN.
- Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change.
- After acknowledgement, lack of additional response within the 90 days period constitutes acceptance of the change.

Vincotech Contact:

Web: www.vincotech.com

Email: PCN_Support@vincotech.com

